BRUHAT BANGALORE MAHANAGARA PALIKE

Name Of Work : Comprehensive Development of Roads & Drains in JP Park, Yeshawanthapura, Jalahalli and Surrounding areas in W No.16, 17 and 37 under PACKAGE- 2022-23 RRN-DIV-(15).

Pre-Measurement Sheet

2nd and Final Bill

Item No:	1	
Item Name:	Removing & Refixing stone slabs of drains and pointing in C.M (1:3) Data Rate	

SLNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	BI (m)	Avg B (m)	D (m)	QTY	REMARKS
								Add 1st RA Bill Qty 23636.94	Sqm
								Total Qty Work Done 23636.94	Sqm
								DPQ of 1st RA Bill Qty 23636.94	Sqm
								Qty Payable in this bill 0.00	Sqm

For SAPIENCE CONSULTANTS

Contractor Representative

Consultant Representative
Authorised Signatory

Assistant Engineer
BBMP

Asst.Executive Engineer
Yeshwanthpura Sub-Division
BBMP

Scanned with CamScanner

BRUHAT BANGALORE MAHANAGARA PALIKE

Name Of Work : Comprehensive Development of Roads & Drains in JP Park, Yeshawanthapura, Jalahalli and Surrounding areas in W No.16, 17 and 37 under PACKAGE- 2022-23 RRN-DIV-(15).

Pre-Measurement Sheet

2nd and Final Bill

Item No: **2**

Item Name: Earth work excavation by manual means for drains,canals, waste weir, draft, approach channels, key trenches, foundation of bridges and such simillar works in all kinds of soils , as per drawing and technical specifications, including setting out, shoring, strutting, barricading, caution lights, removal of stumps and other deleterious matter, excavated surface leveled and sides neatly dressed disposing off the excavated stuff or sorting & stacking the selected stuff for reuse in a radius of 50 m and lift upto 1.5 m including cost of labour, tools & other appurtenaces required to complete the work.In all kinds of soils Depth upto 1.5 m.Item No.1.4.1,Page No.A(5), Vol I CSR 21-22

SLNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
							Add 1st RA Bill Qty	**17634.54**	**Cum**
							Total Qty Work Done	**17634.54**	**Cum**
							DPQ of 1st RA Bill Qty	**17634.54**	**Cum**
							Qty Payable in this bill	**0.00**	**Cum**

For SAPIENCE CONSULTANTS

Authorised Signatory
Consultant Representative

Contractor Representative

Assistant Engineer
BBMP

Asst.Executive Engineer
Yeshwanthpura Sub-Division
BBMP

Scanned with CamScanner

BRUHAT BANGALORE MAHANAGARA PALIKE

Name Of Work : Comprehensive Development of Roads & Drains in JP Park, Yeshawanthapura, Jalahalli and Surrounding areas in W No.16, 17 and 37 under PACKAGE- 2022-23 RRN-DIV-(15).

Pre-Measurement Sheet

2nd and Final Bill

Item No:	3
Item Name:	Providing and laying in position plain cement concrete Mix 1:3:6 (M10) Using 40 mm nominal size graded crushed coarse aggregates for levelling course for all works in foundation. The granite/trap/basalt crushed graded coarse aggregates and fine aggregates as per relevant IS Codes machine mixed, laid in layers not exceeding 150 mm thickness, well compacted using plate vibrators, including all lead & lifts, cost of all materials of quality, labour, Usage charges of machineries, curing, and all the other appurtenances required to complete the work as per technical specifications. (The cost of steel reinforcement & formwork shall be paid separately) (KWPD 2021-22, V I, Item No.2.1.3, Page No.15)

SLNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
							Add 1st RA Bill Qty	162.70	Cum
							Total Qty Work Done	162.70	Cum
							DPQ of 1st RA Bill Qty	162.70	Cum
							Qty Payable in this bill	0.00	Cum

For SAPIENCE CONSULTANTS

Contractor Representative

Authorised Signatory
Consultant Representative

Assistant Engineer
BBMP

Asst.Executive Engineer
Yeshwanthpura Sub-Division
BBMP

Scanned with CamScanner

BRUHAT BANGALORE MAHANAGARA PALIKE

Name Of Work : Comprehensive Development of Roads & Drains in JP Park, Yeshawanthapura, Jalahalli and Surrounding areas in W No.16, 17 and 37 under PACKAGE- 2022-23 RRN-DIV-(15).

Pre-Measurement Sheet

2nd and Final Bill

Item No: 4

Item Name: Providing and constructing load bearing wall with Solid Concrete blocks of size 400x200x200mm having block density more than 1800kg/m3 and minimum compressive strength of 4.00 N/mm2 conforming to IS 2185 (Part - I) - 2005 and constructed with CM 1:4 as per IS 2572:2005 including cost of all materials, labour, scaffolding and curing, usage charges of machinery etc complete as per specifications.I.No 6.32 P.No 17 Volume 2 SR 2021-22

SLNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
							Add 1st RA Bill Qty	13610.70	Sqm
							Total Qty Work Done	13610.70	Sqm
							DPQ of 1st RA Bill Qty	13610.70	Sqm
							Qty Payable in this bill	0.00	Sqm

For SAPIENCE CONSULTANTS

Authorised Signatory

Consultant Representative

Contractor Representative

Assistant Engineer

BBMP

Asst.Executive Engineer

Yeshwanthpura Sub-Division

BBMP

Scanned with CamScanner

BRUHAT BANGALORE MAHANAGARA PALIKE

Name Of Work : Comprehensive Development of Roads & Drains in JP Park, Yeshawanthapura, Jalahalli and Surrounding areas in W No.16, 17 and 37 under PACKAGE- 2022-23 RRN-DIV-(15).

Pre-Measurement Sheet

2nd and Final Bill

Item No:	5								
Item Name:	Providing Flush/ Ruled pointing: Pointing on stone work with cement mortar 1:3 (1 cement : 3 fine sand) after raking joints to depth nicely lining, including cost of materials, labour, curing as per specifications and as per directions of Engineer-in-charge.Item No.8.19.1,Page No.44, Vol II SR 21-22								
SLNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	BI (m)	Avg B (m)	D (m)	QTY	REMARKS
								Add 1st RA Bill Qty 10787.18	Sqm
								Total Qty Work Done 10787.18	Sqm
								DPQ of 1st RA Bill Qty 10787.18	Sqm
								Qty Payable in this bill 0.00	Sqm

For SAPIENCE CONSULTANTS

Authorised Signatory
Consultant Representative

Contractor Representative

Assistant Engineer
BBMP

Asst.Executive Engineer
Yeshwanthpura Sub-Division
BBMP

Scanned with CamScanner

BRUHAT BANGALORE MAHANAGARA PALIKE

ame Of Work : Comprehensive Development of Roads & Drains in JP Park, Yeshawanthapura, Jalahalli and Surrounding areas W No.16, 17 and 37 under PACKAGE- 2022-23 RRN-DIV-(15).

Pre-Measurement Sheet

2nd and Final Bill

Item No: 6

Item Name: Providing and laying in position plain cement concrete for levelling course for all works in foundation. The granite/trap/basalt crushed graded coarse aggregates and fine aggregates as per relevant IS Codes machine mixed, laid in layers not exceeding 150 mm thickness, well compacted using plate vibrators, including all lead & lifts, cost of all materials of quality, labour, Usage charges of machineries, curing, and all the other appurtenances required to complete the work as per technical specifications. (The cost of steel reinforcement & formwork shall be paid separately).Mix 1:3:6 (M10) Using 20 mm nominal size graded crushed coarse aggregate.Item No.2.1.4,Page No.15, Vol I SR 21-22

SLNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	BI (m)	Avg B (m)	D	QTY	REMARKS
								Add 1st RA Bill Qty	945.78 Cum
								Total Qty Work Done	945.78 Cum
								DPQ of 1st RA Bill Qty	945.78 Cum
								Qty Payable in this bill	0.00 Cum

For SAPIENCE CONSULTANTS

Authorised Signatory
Consultant Representative

Contractor Representative

Assistant Engineer
BBMP

Asst.Executive Engineer
Yeshwanthpura Sub-Division
BBMP

Scanned with CamScanner

BRUHAT BANGALORE MAHANAGARA PALIKE

Name Of Work : Comprehensive Development of Roads & Drains in JP Park, Yeshawanthapura, Jalahalli and Surrounding areas W No.16, 17 and 37 under PACKAGE- 2022-23 RRN-DIV-(15).

Pre-Measurement Sheet

2nd and Final Bill

Item No: 7

Item Name: Providing B S Slabs of selected quality roughly dressed having a size of 10cms thick and fixed in cement mortar (1:6) including fixing curing etc., complete.as directed by the Engineer in Charge of the work (Excluding GST and Area Leading Charges)

SLNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	BI (m)	Avg B (m)	D (m)	QTY	REMARKS
							Add 1st RA Bill Qty	**13892.46**	**Sqm**
							Total Qty Work Done	**13892.46**	**Sqm**
							DPQ of 1st RA Bill Qty	**13892.46**	**Sqm**
							Qty Payable in this bill	**0.00**	**Sqm**

For SAPIENCE CONSULTANTS

Contractor Representative

Authorised Signatory
Consultant Representative

Assistant Engineer
BBMP

Asst.Executive Engineer
Yeshwanthpura Sub-Division
BBMP

Scanned with CamScanner

BRUHAT BANGALORE MAHANAGARA PALIKE

e Of Work : Comprehensive Development of Roads & Drains in JP Park, Yeshawanthapura, Jalahalli and Surrounding in W No.16, 17 and 37 under PACKAGE- 2022-23 RRN-DIV-(15).

Pre-Measurement Sheet

2nd and Final Bill

No:	8									
em	Providing one line dressing to granite stone slab / granite stone masonry as per specifications. as directed by the Engineer in Charge of the work (Excluding GST and Area Leading Charges)									
NO	CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS	
								Add 1st RA Bill Qty	13892.46	Sqm
								Total Qty Work Done	13892.46	Sqm
								DPQ of 1st RA Bill Qty	13892.46	Sqm
								Qty Payable in this bill	0.00	Sqm

For SAPIENCE CONSULTANTS

Contractor Representative

Authorised Signatory
Consultant Representative

Assistant Engineer
BBMP

Asst.Executive Engineer
Yeshwanthpura Sub-Division
BBMP

Scanned with CamScanner

BRUHAT BANGALORE MAHANAGARA PALIKE

ne Of Work : Comprehensive Development of Roads & Drains in JP Park, Yeshawanthapura, Jalahalli and Surrounding areas in W '6, 17 and 37 under PACKAGE- 2022-23 RRN-DIV-(15).

Pre-Measurement Sheet

2nd and Final Bill

m No:	9
tem ame:	Providing Machine Cutting edges to B S Slabs 2.5cms.wide as per Specifications.(Only Chamfered length Shall be recorded)inclusive of all taxes Complete.,as directed by the Engineer in Charge of the work (Excluding GST and Area Leading Charges)

LNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
							Add 1st RA Bill Qty	34731.00	Mtr
							Total Qty Work Done	34731.00	Mtr
							DPQ of 1st RA Bill Qty	34731.00	Mtr
							Qty Payable in this bill	0.00	Mtr

For SAPIENCE CONSULTANTS

Contractor Representative

Authorised Signatory
Consultant Representative

Assistant Engineer
BBMP

Asst.Executive Engineer
Yeshwanthpura Sub-Division
BBMP

Scanned with CamScanner

BRUHAT BANGALORE MAHANAGARA PALIKE

Name Of Work : Comprehensive Development of Roads & Drains in JP Park, Yeshawanthapura, Jalahalli and surrounding areas in W No.16, 17 and 37 under PACKAGE- 2022-23 RRN-DIV-(15).

Pre-Measurement Sheet

2nd and Final Bill

Item No: **10**

Item Name: Providing 20 mm cement plaster of mix :1:4 (1 cement: 4 fine sand) to brick/stone masonary including rounding off corners wherever required smooth rendering, providing and removing scaffolding, including cost of materials, labour, curing complete as per specifications and as per directions of Engineer-in-charge. (KWPD 2021-22, V-II, Item No.8.3.1, Page No.41)

SLNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
							Add 1st RA Bill Qty	2169.36	Sqm
							Total Qty Work Done	2169.36	Sqm
							DPQ of 1st RA Bill Qty	2169.36	Sqm
							Qty Payable in this bill	0.00	Sqm

Contractor Representative

Assistant Engineer
BBMP

For SAPIENCE CONSULTANTS
Consultant Representative

Authorised Signatory

Asst.Executive Engineer
Yeshwanthpura Sub-Division
BBMP

Scanned with CamScanner

BRUHAT BANGALORE MAHANAGARA PALIKE

e Of Work : Comprehensive Development of Roads & Drains in JP Park, Yeshawanthapura, Jalahalli and rounding areas in W No.16, 17 and 37 under PACKAGE1 2022123 RRN1DIV1(15).

Pre1Measurement Sheet

2nd and Final Bill

n No: **11**

em: Providing & laying precast drain corner cover slab of 200 mm thickness in CM 1:3 including cost of all materials, labour, curing, transportation, loading, unloading etc, complete as per the directions of the Engineer In Charge.(1.2 x 0.20) Approved Data rate

LNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
							Add 1st RA Bill Qty	379.00	Nos
							Total Qty Work Done	379.00	Nos
							DPQ of 1st RA Bill Qty	379.00	Nos
							Qty Payable in this bill	0.00	Nos

Contractor Representative

Assistant Engineer

BBMP

For SAPIENCE CONSULTANTS

Consultant Representative

Authorised Signatory

Asst.Executive Engineer

Yeshwanthpura Sub-Division

BBMP

Scanned with CamScanner

BRUHAT BANGALORE MAHANAGARA PALIKE

Name Of Work : Comprehensive Development of Roads & Drains in JP Park, Yeshawanthapura, Jalahalli and Surrounding areas in W No.16, 17 and 37 under PACKAGE- 2022-23 RRN-DIV-(15).

Pre-Measurement Sheet

2nd and Final Bill

Item No:	12
Item Name:	Providing & laying precast drain corner cover slab of 200 mm thickness in CM 1:3 including cost of all materials, labour, curing, transportation, loading, unloading etc, complete as per the directions of the Engineer In Charge.(0.9 x 0.20) Approved Data rate

SLNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
								Add 1st RA Bill Qty	800.00	Nos
								Total Qty Work Done	800.00	Nos
								DPQ of 1st RA Bill Qty	800.00	Nos
								Qty Payable in this bill	0.00	Nos

Contractor Representative

Assistant Engineer
BBMP

For SAPIENCE CONSULTANTS

Consultant Representative
Authorised Signatory

Asst.Executive Engineer
Yeshwanthpura Sub-Division
BBMP

Scanned with CamScanner

ARD- 17 BRUHAT BENGALURU MAHANAGARA PALIKE

BRUHAT BANGALORE MAHANAGARA PALIKE

e Of Work : Comprehensive Development of Roads & Drains in JP Park, Yeshawanthapura, Jalahalli and ounding areas in W No.16, 17 and 37 under PACKAGE- 2022-23 RRN-DIV-(15).

Pre-Measurement Sheet

2nd and Final Bill

n No:	13
tem me:	Providing & laying precast drain slab of 230 mm thickness in CM 1:3 including cost of all materials, labour, curing, transportation, loading, unloading etc, complete as per the directions of the Engineer In Charge.(1.2 x 0.23) Approved Data rate

NO	CHAINAGE / Land Mark	NO	L (m)	B (m)	BI (m)	Avg B (m)	D (m)	QTY	REMARKS
							Add 1st RA Bill Qty	36.95	Sqm
							Total Qty Work Done	36.95	Sqm
							DPQ of 1st RA Bill Qty	36.95	Sqm
							Qty Payable in this bill	0.00	Sqm

For SAPIENCE CONSULTANTS

Authorised Signatory
Consultant Representative

Contractor Representative

Assistant Engineer
BBMP

Asst.Executive Engineer
Yeshwanthpura Sub-Division
BBMP

Scanned with CamScanner

WARD- 17 BRUHAT BENGALORE

BRUHAT BANGALORE MAHANAGARA PALIKE

ne Of Work : Comprehensive Development of Roads & Drains in JP Park, Yeshawanthapura, Jalahalli and rounding areas in W No.16, 17 and 37 under PACKAGE- 2022-23 RRN-DIV-(15).

Pre-Measurement Sheet

2nd and Final Bill

m No:	14		
tem ame:	Removing and resetting of kerb stones.Page No. 270		
	Add 1st RA Bill Qty	**14696.76**	**Mtr**
	Total Qty Work Done	**14696.76**	**Mtr**
	DPQ of 1st RA Bill Qty	**14696.76**	**Mtr**
	Qty Payable in this bill	**0.00**	**Mtr**

For SAPIENCE CONSULTANTS

Authorised Signatory

Contractor Representative

Consultant Representative

Assistant Engineer

BBMP

Asst.Executive Engineer
Yeshwanthpura Sub-Division
BBMP

Scanned with CamScanner

BRUHAT BANGALORE MAHANAGARA PALIKE

e Of Work : Comprehensive Development of Roads & Drains in JP Park, Yeshawanthapura, Jalahalli and unding areas in W No.16, 17 and 37 under PACKAGE- 2022-23 RRN-DIV-(15).

Pre-Measurement Sheet

2nd and Final Bill

n No: **15**

tem ame: Providing and fixing pre cast solid cement concrete kerb stones made out of M20 with top and bottom width 114 and 165mm respectively,400mm high and 450mm in length finished with CM 1:3 plastering and finishing cutting including formwork,curing including cost of materials,labour charges of machinery,loading and unloading,lead and lift,transportation etc., complete as directed by the Engineer in charge of the work (Excluding GST and Area Leading Charges)

NO	CHAINAGE / Land Mark	NO	L (m)	B (m)	BI (m)	Avg B (m)	D (m)	QTY	REMARKS
							Add 1st RA Bill Qty	19883.64	Nos
							Total Qty Work Done	19883.64	Nos
							DPQ of 1st RA Bill Qty	19883.64	Nos
							Qty Payable in this bill	0.00	Nos

For SAPIENCE CONSULTANTS

Contractor Representative

Authorised Signatory
Consultant Representative

Assistant Engineer

BBMP

Asst.Executive Engineer
Yeshwanthpura Sub-Division
BBMP

Scanned with CamScanner

BRUHAT BANGALORE MAHANAGARA PALIKE

Name Of Work : Comprehensive Development of Roads & Drains in JP Park, Yeshawanthapura, Jalahalli and surrounding areas in W No.16, 17 and 37 under PACKAGE- 2022-23 RRN-DIV-(15).

Pre-Measurement Sheet

2nd and Final Bill

Item No: 16

Item Name: Painting two coats after filling the surface with synthetic enamel paint in all shades on new plastered concrete surfaces.Painting Two Coats on New Concrete Surfaces.Item No.8.1,Page No.56, Vol III SR 21-22

SLNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	BI (m)	Avg B (m)	D (m)	QTY	REMARKS
	Ward No 17								
	Sundar Nagar								
	Corner Slab No 1	2	6.00				0.30	3.60	
	Corner Slab No 2	2	5.40				0.30	3.24	
	Corner Slab No 3	2	5.70				0.30	3.42	
	Corner Slab No 4	2	4.50				0.30	2.70	
	Corner Slab No 5	2	6.60				0.30	3.96	
	Corner Slab No 6	2	5.40				0.30	3.24	
	Corner Slab No 7	2	5.40				0.30	3.24	
	Corner Slab No 8	2	5.70				0.30	3.42	
	Corner Slab No 9	2	7.50				0.30	4.50	
	Corner Slab No 10	2	7.20				0.30	4.32	
	Corner Slab No 11	2	6.00				0.30	3.60	
	Corner Slab No 12	2	5.40				0.30	3.24	
	Corner Slab No 13	2	5.70				0.30	3.42	
	Corner Slab No 14	2	6.60				0.30	3.96	
	Corner Slab No 15	2	7.50				0.30	4.50	
	Corner Slab No 16	2	7.20				0.30	4.32	
	Corner Slab No 17	2	5.40				0.30	3.24	
	Corner Slab No 18	2	6.00				0.30	3.60	
	Corner Slab No 19	2	6.60				0.30	3.96	
	Corner Slab No 20	2	6.00				0.30	3.60	
	Corner Slab No 21	2	5.40				0.30	3.24	
	Corner Slab No 22	2	5.40				0.30	3.24	
	Corner Slab No 23	2	5.70				0.30	3.42	
	Corner Slab No 24	2	6.00				0.30	3.60	
	Corner Slab No 25	2	6.60				0.30	3.96	
	Corner Slab No 26	2	5.40				0.30	3.24	
	Corner Slab No 27	2	6.00				0.30	3.60	
	Corner Slab No 28	2	6.60				0.30	3.96	
	Corner Slab No 29	2	6.60				0.30	3.96	
	Corner Slab No 30	2	6.00				0.30	3.60	
	Corner Slab No 31	2	6.60				0.30	3.96	
	Corner Slab No 32	2	5.70				0.30	3.42	
	Corner Slab No 33	2	6.60				0.30	3.96	
	Corner Slab No 34	2	6.00				0.30	3.60	
	Corner Slab No 35	2	5.40				0.30	3.24	
	Corner Slab No 36	2	5.70				0.30	3.42	
	Corner Slab No 37	2	6.60				0.30	3.96	

Executive Engineer
Rajarajeshwari Nagara Division
BBMP
Bangalore - 560 064.

Scanned with CamScanner

SNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	BI (m)	Avg B (m)	D (m)	QTY	REMARKS
	Corner Slab No 38	2	5.40				0.30	3.24	
	Corner Slab No 39	2	6.00				0.30	3.60	
	Corner Slab No 40	2	6.60				0.30	3.96	
	Corner Slab No 41	2	6.00				0.30	3.60	
	Corner Slab No 42	2	6.60				0.30	3.96	
	Corner Slab No 43	2	5.40				0.30	3.24	
	Corner Slab No 44	2	5.70				0.30	3.42	
	Corner Slab No 45	2	5.40				0.30	3.24	
	Corner Slab No 46	2	6.60				0.30	3.96	
	Corner Slab No 47	2	6.60				0.30	3.96	
	Corner Slab No 48	2	6.00				0.30	3.60	
	Corner Slab No 49	2	6.00				0.30	3.60	
	Corner Slab No 50	2	5.70				0.30	3.42	
	Corner Slab No 51	2	5.40				0.30	3.24	
	Corner Slab No 52	2	6.60				0.30	3.96	
	Corner Slab No 53	2	6.00				0.30	3.60	
	Corner Slab No 54	2	6.60				0.30	3.96	
	Corner Slab No 55	2	5.40				0.30	3.24	
	Corner Slab No 56	2	6.60				0.30	3.96	
	Corner Slab No 57	2	5.70				0.30	3.42	
	Corner Slab No 58	2	5.40				0.30	3.24	
	Gokulam Grand And Mathikere Signals surrounding								
	Corner Slab No 1	2	6.00				0.30	3.60	
	Corner Slab No 2	2	5.40				0.30	3.24	
	Corner Slab No 3	2	5.70				0.30	3.42	
	Corner Slab No 4	2	4.50				0.30	2.70	
	Corner Slab No 5	2	6.60				0.30	3.96	
	Corner Slab No 6	2	5.40				0.30	3.24	
	Corner Slab No 7	2	5.40				0.30	3.24	
	Corner Slab No 8	2	5.70				0.30	3.42	
	Corner Slab No 9	2	7.50				0.30	4.50	
	Corner Slab No 10	2	7.20				0.30	4.32	
	Corner Slab No 11	2	6.00				0.30	3.60	
	Corner Slab No 12	2	5.40				0.30	3.24	
	Corner Slab No 13	2	5.70				0.30	3.42	
	Corner Slab No 14	2	6.60				0.30	3.96	
	Corner Slab No 15	2	7.50				0.30	4.50	
	Corner Slab No 16	2	7.20				0.30	4.32	
	Corner Slab No 17	2	5.40				0.30	3.24	
	Corner Slab No 18	2	6.00				0.30	3.60	
	Corner Slab No 19	2	6.60				0.30	3.96	
	Corner Slab No 20	2	6.00				0.30	3.60	
	Corner Slab No 21	2	5.40				0.30	3.24	
	Corner Slab No 22	2	5.40				0.30	3.24	
	Corner Slab No 23	2	5.70				0.30	3.42	
	Corner Slab No 24	2	6.00				0.30	3.60	
	Corner Slab No 25	2	6.60				0.30	3.96	
	Corner Slab No 26	2	5.40				0.30	3.24	
	Corner Slab No 27	2	6.00				0.30	3.60	

Executive Engineer
Rajarajeshwari Nagara Division
Bruhat Bangalore Mahanagara Palike
Bangalore - 560 054.

Scanned with CamScanner

SLNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	Bl (m)	Avg B (m)	D (m)	QTY	REMARKS
	Corner Slab No 28	2	6.60				0.30	3.96	
	Corner Slab No 29	2	6.60				0.30	3.96	
	Corner Slab No 30	2	6.00				0.30	3.60	
	Corner Slab No 31	2	6.60				0.30	3.96	
	Corner Slab No 32	2	5.70				0.30	3.42	
	Corner Slab No 33	2	6.60				0.30	3.96	
	Corner Slab No 34	2	6.00				0.30	3.60	
	Corner Slab No 35	2	5.40				0.30	3.24	
	Corner Slab No 36	2	5.70				0.30	3.42	
	Corner Slab No 37	2	6.60				0.30	3.96	
	Corner Slab No 38	2	5.40				0.30	3.24	
	Corner Slab No 39	2	6.00				0.30	3.60	
	Corner Slab No 40	2	6.60				0.30	3.96	
	Corner Slab No 41	2	6.00				0.30	3.60	
	Corner Slab No 42	2	6.60				0.30	3.96	
	Corner Slab No 43	2	5.40				0.30	3.24	
	Corner Slab No 44	2	5.70				0.30	3.42	
	Corner Slab No 45	2	6.00				0.30	3.60	
	Corner Slab No 46	2	5.40				0.30	3.24	
	Corner Slab No 47	2	5.70				0.30	3.42	
	Corner Slab No 48	2	4.50				0.30	2.70	
	Corner Slab No 49	2	6.60				0.30	3.96	
	Corner Slab No 50	2	5.40				0.30	3.24	
	Corner Slab No 51	2	5.40				0.30	3.24	
	Corner Slab No 52	2	5.70				0.30	3.42	
	Corner Slab No 53	2	7.50				0.30	4.50	
	Corner Slab No 54	2	7.20				0.30	4.32	
	Corner Slab No 55	2	6.00				0.30	3.60	
	Corner Slab No 56	2	5.40				0.30	3.24	
	Corner Slab No 57	2	5.70				0.30	3.42	
	Corner Slab No 58	2	6.60				0.30	3.96	
	Corner Slab No 59	2	7.50				0.30	4.50	
	Corner Slab No 60	2	7.20				0.30	4.32	
	Corner Slab No 61	2	5.40				0.30	3.24	
	Corner Slab No 62	2	6.00				0.30	3.60	
	Corner Slab No 63	2	6.60				0.30	3.96	
	Corner Slab No 64	2	6.00				0.30	3.60	
	Corner Slab No 65	2	5.40				0.30	3.24	
	Corner Slab No 66	2	5.40				0.30	3.24	
	Corner Slab No 67	2	5.70				0.30	3.42	
	Corner Slab No 68	2	6.00				0.30	3.60	
	Corner Slab No 69	2	6.60				0.30	3.96	
	Corner Slab No 70	2	5.40				0.30	3.24	
	Corner Slab No 71	2	6.00				0.30	3.60	
	Corner Slab No 72	2	6.60				0.30	3.96	
	Corner Slab No 73	2	6.60				0.30	3.96	
	Corner Slab No 74	2	6.00				0.30	3.60	
	Corner Slab No 75	2	6.60				0.30	3.96	
	Corner Slab No 76	2	5.70				0.30	3.42	

Executive Engineer
Rajeshwari Nagara Division
Bruhat Bangalore Mahanagara Palike
Bangalore - 560 064.

Scanned with CamScanner

SLNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	BI (m)	Avg B (m)	D (m)	QTY	REMARKS
	Corner Slab No 77	2	6.60				0.30	3.96	
	Corner Slab No 78	2	6.00				0.30	3.60	
	Corner Slab No 79	2	5.40				0.30	3.24	
	Corner Slab No 80	2	5.70				0.30	3.42	
	Corner Slab No 81	2	6.60				0.30	3.96	
	Corner Slab No 82	2	5.40				0.30	3.24	
	Corner Slab No 83	2	6.00				0.30	3.60	
	Corner Slab No 84	2	6.60				0.30	3.96	
	Corner Slab No 85	2	6.00				0.30	3.60	
	Corner Slab No 86	2	6.60				0.30	3.96	
	Corner Slab No 87	2	5.40				0.30	3.24	
	Corner Slab No 88	2	5.70				0.30	3.42	
	Corner Slab No 89	2	5.40				0.30	3.24	
	Corner Slab No 90	2	6.60				0.30	3.96	
	Corner Slab No 91	2	6.60				0.30	3.96	
	Corner Slab No 92	2	6.00				0.30	3.60	
	Corner Slab No 93	2	6.00				0.30	3.60	
	Corner Slab No 94	2	5.70				0.30	3.42	
	Corner Slab No 95	2	5.40				0.30	3.24	
	Corner Slab No 96	2	6.60				0.30	3.96	
	Corner Slab No 97	2	6.00				0.30	3.60	
	Corner Slab No 98	2	6.60				0.30	3.96	
	Corner Slab No 99	2	5.40				0.30	3.24	
	Corner Slab No 100	2	6.00				0.30	3.60	
	Corner Slab No 101	2	5.40				0.30	3.24	
	Corner Slab No 102	2	5.70				0.30	3.42	
	Corner Slab No 103	2	4.50				0.30	2.70	
	Corner Slab No 104	2	6.60				0.30	3.96	
	Corner Slab No 105	2	5.40				0.30	3.24	
	Corner Slab No 106	2	5.40				0.30	3.24	
	Corner Slab No 107	2	5.70				0.30	3.42	
	Corner Slab No 108	2	7.50				0.30	4.50	
	Corner Slab No 109	2	7.20				0.30	4.32	
	Corner Slab No 110	2	6.00				0.30	3.60	
	Corner Slab No 111	2	5.40				0.30	3.24	
	Corner Slab No 112	2	5.70				0.30	3.42	
	Corner Slab No 113	2	6.60				0.30	3.96	
	Corner Slab No 114	2	7.50				0.30	4.50	
	Corner Slab No 115	2	7.20				0.30	4.32	
	Corner Slab No 116	2	5.40				0.30	3.24	
	Corner Slab No 117	2	6.00				0.30	3.60	
	Corner Slab No 118	2	6.60				0.30	3.96	
	Corner Slab No 119	2	6.00				0.30	3.60	
	Corner Slab No 120	2	5.40				0.30	3.24	
	Corner Slab No 121	2	5.40				0.30	3.24	
	Corner Slab No 122	2	5.70				0.30	3.42	
	Corner Slab No 123	2	6.00				0.30	3.60	
	Corner Slab No 124	2	6.60				0.30	3.96	
	Corner Slab No 125	2	5.40				0.30	3.24	
	Corner Slab No 126	2	6.00				0.30	3.60	

Executive Engineer
Bangalore Nagara Mahanagara Palike
Bangalore - 560/054

Scanned with CamScanner

SLNO	CHAINAGE Land Mark	NO	L (m)	B (m)	BI (m)	Avg B (m)	D (m)	QTY	REMARKS
	Corner Slab No 127	2	6.60				0.30	3.96	
	Corner Slab No 128	2	6.60				0.30	3.96	
	Corner Slab No 129	2	6.00				0.30	3.60	
	Corner Slab No 130	2	6.60				0.30	3.96	
	Corner Slab No 131	2	5.70				0.30	3.42	
	Corner Slab No 132	2	6.60				0.30	3.96	
	Corner Slab No 133	2	6.00				0.30	3.60	
	Corner Slab No 134	2	5.40				0.30	3.24	
	Corner Slab No 135	2	5.70				0.30	3.42	
	Corner Slab No 136	2	6.60				0.30	3.96	
	Corner Slab No 137	2	5.40				0.30	3.24	
	Corner Slab No 138	2	6.00				0.30	3.60	
	Corner Slab No 139	2	6.60				0.30	3.96	
	Corner Slab No 140	2	6.00				0.30	3.60	
	Corner Slab No 141	2	6.60				0.30	3.96	
	Corner Slab No 142	2	5.40				0.30	3.24	
	Corner Slab No 143	2	5.70				0.30	3.42	
	Corner Slab No 144	2	5.40				0.30	3.24	
	Corner Slab No 145	2	6.60				0.30	3.96	
	Corner Slab No 146	2	6.60				0.30	3.96	
	Corner Slab No 147	2	6.00				0.30	3.60	
	Corner Slab No 148	2	6.00				0.30	3.60	
	Corner Slab No 149	2	5.40				0.30	3.24	
	Corner Slab No 150	2	5.70				0.30	3.42	
	Corner Slab No 151	2	4.50				0.30	2.70	
	Corner Slab No 152	2	6.60				0.30	3.96	
	Corner Slab No 153	2	5.40				0.30	3.24	
	Corner Slab No 154	2	5.40				0.30	3.24	
	Corner Slab No 155	2	5.70				0.30	3.42	
	Mathikere Signal And Ganesha Gr		0.00						
	Corner Slab No 1	2	7.20				0.30	4.32	
	Corner Slab No 2	2	6.00				0.30	3.60	
	Corner Slab No 3	2	5.40				0.30	3.24	
	Corner Slab No 4	2	5.70				0.30	3.42	
	Corner Slab No 5	2	6.60				0.30	3.96	
	Corner Slab No 6	2	7.50				0.30	4.50	
	Corner Slab No 7	2	7.20				0.30	4.32	
	Corner Slab No 8	2	5.40				0.30	3.24	
	Corner Slab No 9	2	6.00				0.30	3.60	
	Corner Slab No 10	2	6.60				0.30	3.96	
	Corner Slab No 11	2	6.00				0.30	3.60	
	Corner Slab No 12	2	5.40				0.30	3.24	
	Corner Slab No 13	2	5.40				0.30	3.24	
	Corner Slab No 14	2	5.70				0.30	3.42	
	Corner Slab No 15	2	6.00				0.30	3.60	
	Corner Slab No 16	2	6.60				0.30	3.96	
	Corner Slab No 17	2	5.40				0.30	3.24	
	Corner Slab No 18	2	6.00				0.30	3.60	
	Corner Slab No 19	2	6.60				0.30	3.96	
	Corner Slab No 20	2	6.60				0.30	3.96	

Assistant Engineer
Rajarajeshwari Nagara Division
Bangalore Mahanagara Palike
Bangalore - 560 054.

Scanned with CamScanner

SLNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	Bl (m)	Avg B (m)	D (m)	QTY	REMARKS
	Corner Slab No 21	2	6.00				0.30	3.60	
	Corner Slab No 22	2	6.60				0.30	3.96	
	Corner Slab No 23	2	5.70				0.30	3.42	
	Corner Slab No 24	2	6.60				0.30	3.96	
	Corner Slab No 25	2	6.00				0.30	3.60	
	Corner Slab No 26	2	5.40				0.30	3.24	
	Corner Slab No 27	2	5.70				0.30	3.42	
	Corner Slab No 28	2	6.60				0.30	3.96	
	Corner Slab No 29	2	5.40				0.30	3.24	
	Corner Slab No 30	2	6.00				0.30	3.60	
	Corner Slab No 31	2	6.60				0.30	3.96	
	Corner Slab No 32	2	6.00				0.30	3.60	
	Corner Slab No 33	2	6.60				0.30	3.96	
	Corner Slab No 34	2	5.40				0.30	3.24	
	Corner Slab No 35	2	5.70				0.30	3.42	
	Corner Slab No 36	2	5.40				0.30	3.24	
	Corner Slab No 37	2	6.60				0.30	3.96	
	Corner Slab No 38	2	6.60				0.30	3.96	
	Corner Slab No 39	2	6.00				0.30	3.60	
	Corner Slab No 40	2	6.00				0.30	3.60	
	Corner Slab No 41	2	5.70				0.30	3.42	
	Corner Slab No 42	2	5.40				0.30	3.24	
	Corner Slab No 43	2	6.60				0.30	3.96	
	Corner Slab No 44	2	6.00				0.30	3.60	
	Corner Slab No 45	2	6.60				0.30	3.96	
	Corner Slab No 46	2	6.00				0.30	3.60	
	Corner Slab No 47	2	5.40				0.30	3.24	
	Corner Slab No 48	2	5.70				0.30	3.42	
	Corner Slab No 49	2	4.50				0.30	2.70	
	Corner Slab No 50	2	6.60				0.30	3.96	
	Corner Slab No 51	2	5.40				0.30	3.24	
	Corner Slab No 52	2	5.40				0.30	3.24	
	Corner Slab No 53	2	5.70				0.30	3.42	
	Corner Slab No 54	2	7.50				0.30	4.50	
	Corner Slab No 55	2	7.20				0.30	4.32	
	Corner Slab No 56	2	6.00				0.30	3.60	
	Corner Slab No 57	2	5.40				0.30	3.24	
	Corner Slab No 58	2	5.70				0.30	3.42	
	Corner Slab No 59	2	6.60				0.30	3.96	
	Corner Slab No 60	2	7.50				0.30	4.50	
	Corner Slab No 61	2	7.20				0.30	4.32	
	Corner Slab No 62	2	5.40				0.30	3.24	
	Corner Slab No 63	2	6.00				0.30	3.60	
	Corner Slab No 64	2	6.60				0.30	3.96	
	Corner Slab No 65	2	6.00				0.30	3.60	
	Corner Slab No 66	2	5.40				0.30	3.24	
	Corner Slab No 67	2	5.40				0.30	3.24	
	Corner Slab No 68	2	5.70				0.30	3.42	
	Corner Slab No 69	2	6.00				0.30	3.60	

Executive Engineer
Bangalore Division
Bangalore - 560 054.

Scanned with CamScanner

SLNO	CHAINAGE Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
	Corner Slab No 70	2	6.60				0.30	3.96	
	Corner Slab No 71	2	5.40				0.30	3.24	
	Corner Slab No 72	2	6.00				0.30	3.60	
	Corner Slab No 73	2	6.60				0.30	3.96	
	Corner Slab No 74	2	6.60				0.30	3.96	
	Corner Slab No 75	2	6.00				0.30	3.60	
	Corner Slab No 76	2	6.60				0.30	3.96	
	Corner Slab No 77	2	5.70				0.30	3.42	
	Corner Slab No 78	2	6.60				0.30	3.96	
	Corner Slab No 79	2	6.00				0.30	3.60	
	Corner Slab No 80	2	5.40				0.30	3.24	
	Corner Slab No 81	2	5.70				0.30	3.42	
	Corner Slab No 82	2	6.60				0.30	3.96	
	Corner Slab No 83	2	5.40				0.30	3.24	
	Corner Slab No 84	2	6.00				0.30	3.60	
	Corner Slab No 85	2	6.60				0.30	3.96	
	Corner Slab No 86	2	6.00				0.30	3.60	
	Corner Slab No 87	2	6.60				0.30	3.96	
	Corner Slab No 88	2	5.40				0.30	3.24	
	Corner Slab No 89	2	5.70				0.30	3.42	
	Corner Slab No 90	2	5.40				0.30	3.24	
	Corner Slab No 91	2	6.60				0.30	3.96	
	Corner Slab No 92	2	6.60				0.30	3.96	
	Corner Slab No 93	2	6.00				0.30	3.60	
	Corner Slab No 94	2	6.00				0.30	3.60	
	Corner Slab No 95	2	5.40				0.30	3.24	
	Corner Slab No 96	2	5.70				0.30	3.42	
	Corner Slab No 97	2	4.50				0.30	2.70	
	Corner Slab No 98	2	6.60				0.30	3.96	
	Corner Slab No 99	2	5.40				0.30	3.24	
	Corner Slab No 100	2	5.40				0.30	3.24	
	Corner Slab No 101	2	5.70				0.30	3.42	
	Corner Slab No 102	2	7.50				0.30	4.50	
	Corner Slab No 103	2	7.20				0.30	4.32	
	Corner Slab No 104	2	6.00				0.30	3.60	
	Corner Slab No 105	2	5.40				0.30	3.24	
	Corner Slab No 106	2	5.70				0.30	3.42	
	Corner Slab No 107	2	6.60				0.30	3.96	
	Corner Slab No 108	2	7.50				0.30	4.50	
	Corner Slab No 109	2	7.20				0.30	4.32	
	Corner Slab No 110	2	5.40				0.30	3.24	
	Corner Slab No 111	2	6.00				0.30	3.60	
	Corner Slab No 112	2	6.60				0.30	3.96	
	Corner Slab No 113	2	6.00				0.30	3.60	
	Corner Slab No 114	2	5.40				0.30	3.24	
	Corner Slab No 115	2	5.40				0.30	3.24	
	Corner Slab No 116	2	5.70				0.30	3.42	
	Corner Slab No 117	2	6.00				0.30	3.60	
	Corner Slab No 118	2	6.60				0.30	3.96	
	Corner Slab No 119	2	5.40				0.30	3.24	

Executive Engineer
Electrical Division
Belagavi Range Belagavi

Scanned with CamScanner

SLNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	Bl (m)	Avg B (m)	D (m)	QTY	REMARKS
	Corner Slab No 120	2	6.00				0.30	3.60	
	Corner Slab No 121	2	6.60				0.30	3.96	
	Corner Slab No 122	2	6.60				0.30	3.96	
	Corner Slab No 123	2	6.00				0.30	3.60	
	Corner Slab No 124	2	6.60				0.30	3.96	
	Corner Slab No 125	2	5.70				0.30	3.42	
	Corner Slab No 126	2	6.60				0.30	3.96	
	Corner Slab No 127	2	6.00				0.30	3.60	
	Corner Slab No 128	2	5.40				0.30	3.24	
	Corner Slab No 129	2	5.70				0.30	3.42	
	Corner Slab No 130	2	6.60				0.30	3.96	
	Corner Slab No 131	2	5.40				0.30	3.24	
	Corner Slab No 132	2	6.00				0.30	3.60	
	Corner Slab No 133	2	6.60				0.30	3.96	
	Corner Slab No 134	2	6.00				0.30	3.60	
	Corner Slab No 135	2	6.60				0.30	3.96	
	Corner Slab No 136	2	5.40				0.30	3.24	
	Corner Slab No 137	2	5.70				0.30	3.42	
	Corner Slab No 138	2	5.40				0.30	3.24	
	Corner Slab No 139	2	6.60				0.30	3.96	
	Corner Slab No 140	2	6.60				0.30	3.96	
	Corner Slab No 141	2	6.00				0.30	3.60	
	Corner Slab No 142	2	6.00				0.30	3.60	
	Corner Slab No 143	2	5.70				0.30	3.42	
	Corner Slab No 144	2	5.40				0.30	3.24	
	Corner Slab No 145	2	6.60				0.30	3.96	
	Corner Slab No 146	2	6.00				0.30	3.60	
	Corner Slab No 147	2	6.00				0.30	3.60	
	Corner Slab No 148	2	5.40				0.30	3.24	
	Corner Slab No 149	2	5.70				0.30	3.42	
	Corner Slab No 150	2	4.50				0.30	2.70	
	Corner Slab No 151	2	6.60				0.30	3.96	
	Corner Slab No 152	2	5.40				0.30	3.24	
	Corner Slab No 153	2	5.40				0.30	3.24	
	Corner Slab No 154	2	5.70				0.30	3.42	
	Corner Slab No 155	2	7.50				0.30	4.50	
	Corner Slab No 156	2	7.20				0.30	4.32	
	Corner Slab No 157	2	6.00				0.30	3.60	
	Corner Slab No 158	2	5.40				0.30	3.24	
	Corner Slab No 159	2	5.70				0.30	3.42	
	Corner Slab No 160	2	6.60				0.30	3.96	
	Corner Slab No 161	2	7.50				0.30	4.50	
	Corner Slab No 162	2	7.20				0.30	4.32	
	Corner Slab No 163	2	5.40				0.30	3.24	
	Corner Slab No 164	2	6.00				0.30	3.60	
	Corner Slab No 165	2	6.60				0.30	3.96	
	Corner Slab No 166	2	6.00				0.30	3.60	
	Corner Slab No 167	2	5.40				0.30	3.24	
	Corner Slab No 168	2	5.40				0.30	3.24	
	Corner Slab No 169	2	5.70				0.30	3.42	

Executive Engineer
Upper Tunga Canal Division
Malavalli, Mandya Malavalli Taluk
Tungabhadra Nagara - 583 054

Scanned with CamScanner

SL NO	CHAINAGE Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
	Corner Slab No 170	2	6.00				0.30	3.60	
	Corner Slab No 171	2	6.60				0.30	3.96	
	Corner Slab No 172	2	5.40				0.30	3.24	
	Corner Slab No 173	2	6.00				0.30	3.60	
	Corner Slab No 174	2	6.60				0.30	3.96	
	Corner Slab No 175	2	6.60				0.30	3.96	
	Corner Slab No 176	2	6.00				0.30	3.60	
	Corner Slab No 177	2	6.60				0.30	3.96	
	Corner Slab No 178	2	5.70				0.30	3.42	
	Corner Slab No 179	2	6.60				0.30	3.96	
	Corner Slab No 180	2	6.00				0.30	3.60	
	Corner Slab No 181	2	5.40				0.30	3.24	
	Corner Slab No 182	2	5.70				0.30	3.42	
	Corner Slab No 183	2	6.60				0.30	3.96	
	Corner Slab No 184	2	5.40				0.30	3.24	
	Corner Slab No 185	2	6.00				0.30	3.60	
	Corner Slab No 186	2	6.60				0.30	3.96	
	Corner Slab No 187	2	6.00				0.30	3.60	
	Corner Slab No 188	2	6.60				0.30	3.96	
	Corner Slab No 189	2	5.40				0.30	3.24	
	Corner Slab No 190	2	5.70				0.30	3.42	
	Corner Slab No 191	2	5.40				0.30	3.24	
	Mohan Kumar Nagar 74								
	Corner Slab No 1	2	6.60				0.30	3.96	
	Corner Slab No 2	2	6.00				0.30	3.60	
	Corner Slab No 3	2	6.00				0.30	3.60	
	Corner Slab No 4	2	5.70				0.30	3.42	
	Corner Slab No 5	2	5.40				0.30	3.24	
	Corner Slab No 6	2	6.60				0.30	3.96	
	Corner Slab No 7	2	6.00				0.30	3.60	
	Corner Slab No 8	2	5.40				0.30	3.24	
	Corner Slab No 9	2	5.70				0.30	3.42	
	Corner Slab No 10	2	4.50				0.30	2.70	
	Corner Slab No 11	2	6.60				0.30	3.96	
	Corner Slab No 12	2	5.40				0.30	3.24	
	Corner Slab No 13	2	5.40				0.30	3.24	
	Corner Slab No 14	2	5.70				0.30	3.42	
	Corner Slab No 15	2	7.50				0.30	4.50	
	Corner Slab No 16	2	7.20				0.30	4.32	
	Corner Slab No 17	2	6.00				0.30	3.60	
	Corner Slab No 18	2	5.40				0.30	3.24	
	Corner Slab No 19	2	5.70				0.30	3.42	
	Corner Slab No 20	2	6.60				0.30	3.96	
	Corner Slab No 21	2	7.50				0.30	4.50	
	Corner Slab No 22	2	7.20				0.30	4.32	
	Corner Slab No 23	2	5.40				0.30	3.24	
	Corner Slab No 24	2	6.00				0.30	3.60	
	Corner Slab No 25	2	6.60				0.30	3.96	
	Corner Slab No 26	2	6.00				0.30	3.60	

Executive Engineer
Rajajinagar Division
Bruhat Bangalore Mahanagara Palike
Bangalore 560 054

Scanned with CamScanner

S.NO	CHAINAGE Land Mark	NO	L (m)	B (m)	Bl (m)	Avg B (m)	D (m)	QTY	REMARKS
	Corner Slab No 27	2	5.40				0.30	3.24	
	Corner Slab No 28	2	5.40				0.30	3.24	
	Corner Slab No 29	2	5.70				0.30	3.42	
	Corner Slab No 30	2	6.00				0.30	3.60	
	Corner Slab No 31	2	6.60				0.30	3.96	
	Corner Slab No 32	2	5.40				0.30	3.24	
	Corner Slab No 33	2	6.00				0.30	3.60	
	Corner Slab No 34	2	6.60				0.30	3.96	
	Corner Slab No 35	2	6.60				0.30	3.96	
	Corner Slab No 36	2	6.00				0.30	3.60	
	Corner Slab No 37	2	6.60				0.30	3.96	
	Corner Slab No 38	2	5.70				0.30	3.42	
	Corner Slab No 39	2	6.60				0.30	3.96	
	Corner Slab No 40	2	6.00				0.30	3.60	
	Corner Slab No 41	2	5.40				0.30	3.24	
	Corner Slab No 42	2	5.70				0.30	3.42	
	Corner Slab No 43	2	6.60				0.30	3.96	
	Corner Slab No 44	2	5.40				0.30	3.24	
	Corner Slab No 45	2	6.00				0.30	3.60	
	Corner Slab No 46	2	6.60				0.30	3.96	
	Corner Slab No 47	2	6.00				0.30	3.60	
	Corner Slab No 48	2	6.60				0.30	3.96	
	Corner Slab No 49	2	5.40				0.30	3.24	
	Corner Slab No 50	2	5.70				0.30	3.42	
	Corner Slab No 51	2	5.40				0.30	3.24	
	Corner Slab No 52	2	6.60				0.30	3.96	
	Corner Slab No 53	2	6.60				0.30	3.96	
	Corner Slab No 54	2	6.00				0.30	3.60	
	Corner Slab No 55	2	6.00				0.30	3.60	
	Corner Slab No 56	2	5.70				0.30	3.42	
	Corner Slab No 57	2	5.40				0.30	3.24	
	Corner Slab No 58	2	6.60				0.30	3.96	
	Corner Slab No 59	2	6.00				0.30	3.60	
	Corner Slab No 60	2	6.60				0.30	3.96	
	Corner Slab No 61	2	5.40				0.30	3.24	
	Corner Slab No 62	2	6.60				0.30	3.96	
	Corner Slab No 63	2	5.70				0.30	3.42	
	Corner Slab No 64	2	5.40				0.30	3.24	
	Corner Slab No 65	2	6.00				0.30	3.60	
	Corner Slab No 66	2	5.40				0.30	3.24	
	Corner Slab No 67	2	5.70				0.30	3.42	
	Corner Slab No 68	2	4.50				0.30	2.70	
	Corner Slab No 69	2	6.60				0.30	3.96	
	Corner Slab No 70	2	5.40				0.30	3.24	
	Corner Slab No 71	2	5.40				0.30	3.24	
	Corner Slab No 72	2	5.70				0.30	3.42	
	Corner Slab No 73	2	7.50				0.30	4.50	
	Corner Slab No 74	2	7.20				0.30	4.32	
	Corner Slab No 75	2	6.00				0.30	3.60	

Executive Engineer
Parbhani Nagarpalika Division
Parbhani Municipal Council

Scanned with CamScanner

SI.NO	CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
	Corner Slab No 76	2	5.40				0.30	3.24	
	Corner Slab No 77	2	5.70				0.30	3.42	
	Corner Slab No 78	2	6.60				0.30	3.96	
	Corner Slab No 79	2	7.50				0.30	4.50	
	Corner Slab No 80	2	7.20				0.30	4.32	
	Corner Slab No 81	2	5.40				0.30	3.24	
	Corner Slab No 82	2	6.00				0.30	3.60	
	Corner Slab No 83	2	6.60				0.30	3.96	
	Corner Slab No 84	2	6.00				0.30	3.60	
	Corner Slab No 85	2	5.40				0.30	3.24	
	Corner Slab No 86	2	5.40				0.30	3.24	
	Corner Slab No 87	2	5.70				0.30	3.42	
	Corner Slab No 88	2	6.00				0.30	3.60	
	Corner Slab No 89	2	6.60				0.30	3.96	
	Corner Slab No 90	2	5.40				0.30	3.24	
	Corner Slab No 91	2	6.00				0.30	3.60	
	Corner Slab No 92	2	6.60				0.30	3.96	
	Corner Slab No 93	2	6.60				0.30	3.96	
	Corner Slab No 94	2	6.00				0.30	3.60	
	Corner Slab No 95	2	6.60				0.30	3.96	
	Corner Slab No 96	2	5.70				0.30	3.42	
	Corner Slab No 97	2	6.60				0.30	3.96	
	Corner Slab No 98	2	6.00				0.30	3.60	
	Corner Slab No 99	2	5.40				0.30	3.24	
	Corner Slab No 100	2	5.70				0.30	3.42	
	Corner Slab No 101	2	6.60				0.30	3.96	
	Corner Slab No 102	2	5.40				0.30	3.24	
	Corner Slab No 103	2	6.00				0.30	3.60	
	Corner Slab No 104	2	6.60				0.30	3.96	
	Corner Slab No 105	2	6.00				0.30	3.60	
	Corner Slab No 106	2	6.60				0.30	3.96	
	Corner Slab No 107	2	5.40				0.30	3.24	
	Corner Slab No 108	2	5.70				0.30	3.42	
	Corner Slab No 109	2	5.40				0.30	3.24	
	Corner Slab No 110	2	6.60				0.30	3.96	
	Corner Slab No 111	2	6.60				0.30	3.96	
	Corner Slab No 112	2	6.00				0.30	3.60	
	Corner Slab No 113	2	6.00				0.30	3.60	
	Corner Slab No 114	2	5.70				0.30	3.42	
	Corner Slab No 115	2	5.40				0.30	3.24	
	Corner Slab No 116	2	6.60				0.30	3.96	
	Corner Slab No 117	2	6.00				0.30	3.60	
	Corner Slab No 118	2	6.60				0.30	3.96	
	Corner Slab No 119	2	5.40				0.30	3.24	
	Corner Slab No 120	2	6.60				0.30	3.96	
	Corner Slab No 121	2	5.70				0.30	3.42	
	Corner Slab No 122	2	5.40				0.30	3.24	
	Corner Slab No 123	2	6.00				0.30	3.60	
	Corner Slab No 124	2	5.40				0.30	3.24	
	Corner Slab No 125	2	5.70				0.30	3.42	

Assistant Engineer
Rajarajeshwari Nagara Division
Bruhat Bengaluru Mahanagara Palike
Bangalore - 560 054

Scanned with CamScanner

NO	CHAINAGE Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
	Corner Slab No 126	2	4.50				0.30	2.70	
	Corner Slab No 127	2	6.60				0.30	3.96	
	Corner Slab No 128	2	5.40				0.30	3.24	
	Corner Slab No 129	2	5.40				0.30	3.24	
	Corner Slab No 130	2	5.70				0.30	3.42	
	Corner Slab No 131	2	7.50				0.30	4.50	
	Corner Slab No 132	2	7.20				0.30	4.32	
	Corner Slab No 133	2	6.00				0.30	3.60	
	Corner Slab No 134	2	5.40				0.30	3.24	
	Corner Slab No 135	2	5.70				0.30	3.42	
	Corner Slab No 136	2	6.60				0.30	3.96	
	Corner Slab No 137	2	7.50				0.30	4.50	
	Corner Slab No 138	2	7.20				0.30	4.32	
	Corner Slab No 139	2	5.40				0.30	3.24	
	Corner Slab No 140	2	6.00				0.30	3.60	
	Corner Slab No 141	2	6.60				0.30	3.96	
	Corner Slab No 142	2	6.00				0.30	3.60	
	Corner Slab No 143	2	5.40				0.30	3.24	
	Corner Slab No 144	2	5.40				0.30	3.24	
	Corner Slab No 145	2	5.70				0.30	3.42	
	Corner Slab No 146	2	6.00				0.30	3.60	
	Corner Slab No 147	2	6.60				0.30	3.96	
	Corner Slab No 148	2	5.40				0.30	3.24	
	Corner Slab No 149	2	6.00				0.30	3.60	
	Corner Slab No 150	2	6.60				0.30	3.96	
	Corner Slab No 151	2	6.60				0.30	3.96	
	Corner Slab No 152	2	6.00				0.30	3.60	
	Corner Slab No 153	2	6.60				0.30	3.96	
	Corner Slab No 154	2	5.70				0.30	3.42	
	Corner Slab No 155	2	6.60				0.30	3.96	
	Corner Slab No 156	2	6.00				0.30	3.60	
	Corner Slab No 157	2	5.40				0.30	3.24	
	Corner Slab No 158	2	5.70				0.30	3.42	
	Corner Slab No 159	2	6.60				0.30	3.96	
	Corner Slab No 160	2	5.40				0.30	3.24	
	Corner Slab No 161	2	6.00				0.30	3.60	
	Corner Slab No 162	2	6.60				0.30	3.96	
	Corner Slab No 163	2	6.00				0.30	3.60	
	Corner Slab No 164	2	6.60				0.30	3.96	
	Corner Slab No 165	2	5.40				0.30	3.24	
	Corner Slab No 166	2	5.70				0.30	3.42	
	Corner Slab No 167	2	6.00				0.30	3.60	
	Corner Slab No 168	2	5.40				0.30	3.24	
	Corner Slab No 169	2	5.70				0.30	3.42	
	Corner Slab No 170	2	4.50				0.30	2.70	
	Corner Slab No 171	2	6.60				0.30	3.96	
	Corner Slab No 172	2	5.40				0.30	3.24	
	Corner Slab No 173	2	5.40				0.30	3.24	
	Corner Slab No 174	2	5.70				0.30	3.42	
	Corner Slab No 175	2	7.50				0.30	4.50	

Executive Engineer
Rajiv Gandhi Housing Project Division
Krishna Rajapura Mahadevapura Palike
Bangalore - 560 054.

Scanned with CamScanner

NO	CHAINAGE Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
	Corner Slab No 176	2	7.20				0.30	4.32	
	Corner Slab No 177	2	6.00				0.30	3.60	
	Corner Slab No 178	2	5.40				0.30	3.24	
	Corner Slab No 179	2	5.70				0.30	3.42	
	Corner Slab No 180	2	6.60				0.30	3.96	
	Corner Slab No 181	2	7.50				0.30	4.50	
	Corner Slab No 182	2	7.20				0.30	4.32	
	Corner Slab No 183	2	5.40				0.30	3.24	
	Corner Slab No 184	2	6.00				0.30	3.60	
	Corner Slab No 185	2	6.60				0.30	3.96	
	Corner Slab No 186	2	6.00				0.30	3.60	
	Corner Slab No 187	2	5.40				0.30	3.24	
	Corner Slab No 188	2	5.40				0.30	3.24	
	Corner Slab No 189	2	5.70				0.30	3.42	
	Corner Slab No 190	2	6.00				0.30	3.60	
	Corner Slab No 191	2	6.60				0.30	3.96	
	MES Road To Railway Trac								
	Corner Slab No 1	2	6.00						
	Corner Slab No 2	2	6.60				0.30	3.60	
	Corner Slab No 3	2	6.60				0.30	3.96	
	Corner Slab No 4	2	6.00				0.30	3.60	
	Corner Slab No 5	2	6.60				0.30	3.96	
	Corner Slab No 6	2	5.70				0.30	3.42	
	Corner Slab No 7	2	6.60				0.30	3.96	
	Corner Slab No 8	2	6.00				0.30	3.60	
	Corner Slab No 9	2	5.40				0.30	3.24	
	Corner Slab No 10	2	5.70				0.30	3.42	
	Corner Slab No 11	2	6.60				0.30	3.96	
	Corner Slab No 12	2	5.40				0.30	3.24	
	Corner Slab No 13	2	6.00				0.30	3.60	
	Corner Slab No 14	2	6.60				0.30	3.96	
	Corner Slab No 15	2	6.00				0.30	3.60	
	Corner Slab No 16	2	6.60				0.30	3.96	
	Corner Slab No 17	2	5.40				0.30	3.24	
	Corner Slab No 18	2	5.70				0.30	3.42	
	Corner Slab No 19	2	5.40				0.30	3.24	
	Corner Slab No 20	2	6.60				0.30	3.96	
	Corner Slab No 21	2	6.60				0.30	3.96	
	Corner Slab No 22	2	6.00				0.30	3.60	
	Corner Slab No 23	2	6.00				0.30	3.60	
	Corner Slab No 24	2	5.70				0.30	3.42	
	Corner Slab No 25	2	5.40				0.30	3.24	
	Corner Slab No 26	2	6.60				0.30	3.96	
	Corner Slab No 27	2	6.00				0.30	3.60	
	Corner Slab No 28	2	6.60				0.30	3.96	
	Corner Slab No 29	2	5.40				0.30	3.24	
	Corner Slab No 30	2	6.00				0.30	3.60	
	Corner Slab No 31	2	5.40				0.30	3.24	
	Corner Slab No 32	2	5.70				0.30	3.42	

Executive Engineer
Karnataka Vidyuth Karkhane Division
Bangalore Mahanagara Parike
Bangalore - 560 054.

Scanned with CamScanner

NO	CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
	Corner Slab No 33	2	4.50				0.30	2.70	
	Corner Slab No 34	2	6.60				0.30	3.96	
	Corner Slab No 35	2	5.40				0.30	3.24	
	Corner Slab No 36	2	5.40				0.30	3.24	
	Corner Slab No 37	2	5.70				0.30	3.42	
	Corner Slab No 38	2	7.50				0.30	4.50	
	Corner Slab No 39	2	7.20				0.30	4.32	
	Corner Slab No 40	2	6.00				0.30	3.60	
	Corner Slab No 41	2	5.40				0.30	3.24	
	Corner Slab No 42	2	5.70				0.30	3.42	
	Corner Slab No 43	2	6.60				0.30	3.96	
	Corner Slab No 44	2	7.50				0.30	4.50	
	Corner Slab No 45	2	7.20				0.30	4.32	
	Corner Slab No 46	2	5.40				0.30	3.24	
	Corner Slab No 47	2	6.00				0.30	3.60	
	Corner Slab No 48	2	6.60				0.30	3.96	
	Corner Slab No 49	2	6.00				0.30	3.60	
	Corner Slab No 50	2	5.40				0.30	3.24	
	Corner Slab No 51	2	5.40				0.30	3.24	
	Corner Slab No 52	2	5.70				0.30	3.42	
	Corner Slab No 53	2	6.00				0.30	3.60	
	Corner Slab No 54	2	6.60				0.30	3.96	
	Corner Slab No 55	2	5.40				0.30	3.24	
	Corner Slab No 56	2	6.00				0.30	3.60	
	Corner Slab No 57	2	6.60				0.30	3.96	
	Corner Slab No 58	2	6.60				0.30	3.96	
	Corner Slab No 59	2	6.00				0.30	3.60	
	Corner Slab No 60	2	6.60				0.30	3.96	
	Corner Slab No 61	2	5.70				0.30	3.42	
	Corner Slab No 62	2	6.60				0.30	3.96	
	Corner Slab No 63	2	6.00				0.30	3.60	
	Corner Slab No 64	2	5.40				0.30	3.24	
	Corner Slab No 65	2	5.70				0.30	3.42	
	Corner Slab No 66	2	6.60				0.30	3.96	
	Corner Slab No 67	2	5.40				0.30	3.24	
	Corner Slab No 68	2	6.00				0.30	3.60	
	Corner Slab No 69	2	6.60				0.30	3.96	
	Corner Slab No 70	2	6.00				0.30	3.60	
	Corner Slab No 71	2	6.60				0.30	3.96	
	Corner Slab No 72	2	5.40				0.30	3.24	
	Corner Slab No 73	2	5.70				0.30	3.42	
	Corner Slab No 74	2	5.40				0.30	3.24	
	Corner Slab No 75	2	6.60				0.30	3.96	
	Corner Slab No 76	2	6.60				0.30	3.96	
	Corner Slab No 77	2	6.00				0.30	3.60	
	Corner Slab No 78	2	6.00				0.30	3.60	
	Corner Slab No 79	2	5.40				0.30	3.24	
	Corner Slab No 80	2	5.70				0.30	3.42	
	Corner Slab No 81	2	4.50				0.30	2.70	
	Corner Slab No 82	2	6.60				0.30	3.96	

Executive Engineer
Irrigation Department, Maligawa Division
Irrigation Complex, Mahanonata Veediya
Kandy. 081-2234054.

Scanned with CamScanner

CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 83	2	5.40				0.30	3.24	
Corner Slab No 84	2	5.40				0.30	3.24	
Corner Slab No 85	2	5.70				0.30	3.42	
Corner Slab No 86	2	7.50				0.30	4.50	
Corner Slab No 87	2	7.20				0.30	4.32	
Corner Slab No 88	2	6.00				0.30	3.60	
Corner Slab No 89	2	5.40				0.30	3.24	
Corner Slab No 90	2	5.70				0.30	3.42	
Corner Slab No 91	2	6.60				0.30	3.96	
Corner Slab No 92	2	7.50				0.30	4.50	
Corner Slab No 93	2	7.20				0.30	4.32	
Corner Slab No 94	2	5.40				0.30	3.24	
Corner Slab No 95	2	6.00				0.30	3.60	
Corner Slab No 96	2	6.60				0.30	3.96	
Corner Slab No 97	2	6.00				0.30	3.60	
Corner Slab No 98	2	5.40				0.30	3.24	
Corner Slab No 99	2	5.40				0.30	3.24	
Corner Slab No 100	2	5.70				0.30	3.42	
Corner Slab No 101	2	6.00				0.30	3.60	
Corner Slab No 102	2	6.60				0.30	3.96	
Corner Slab No 103	2	5.40				0.30	3.24	
Corner Slab No 104	2	6.00				0.30	3.60	
Corner Slab No 105	2	6.60				0.30	3.96	
Corner Slab No 106	2	6.60				0.30	3.96	
Corner Slab No 107	2	6.00				0.30	3.60	
Corner Slab No 108	2	6.60				0.30	3.96	
Corner Slab No 109	2	5.70				0.30	3.42	
Corner Slab No 110	2	6.60				0.30	3.96	
Corner Slab No 111	2	6.00				0.30	3.60	
Corner Slab No 112	2	5.40				0.30	3.24	
Corner Slab No 113	2	5.70				0.30	3.42	
Corner Slab No 114	2	6.60				0.30	3.96	
Corner Slab No 115	2	5.40				0.30	3.24	
Corner Slab No 116	2	6.00				0.30	3.60	
Corner Slab No 117	2	6.60				0.30	3.96	
Corner Slab No 118	2	6.00				0.30	3.60	
Corner Slab No 119	2	6.60				0.30	3.96	
Corner Slab No 120	2	5.40				0.30	3.24	
Corner Slab No 121	2	5.70				0.30	3.42	
Corner Slab No 122	2	5.40				0.30	3.24	
Corner Slab No 123	2	6.60				0.30	3.96	
Corner Slab No 124	2	6.60				0.30	3.96	
Corner Slab No 125	2	6.00				0.30	3.60	
Corner Slab No 126	2	6.00				0.30	3.60	
Corner Slab No 127	2	5.70				0.30	3.42	
Corner Slab No 128	2	5.40				0.30	3.24	
Corner Slab No 129	2	6.60				0.30	3.96	
Corner Slab No 130	2	6.00				0.30	3.60	
Corner Slab No 131	2	6.60				0.30	3.96	
Corner Slab No 132	2	6.00				0.30	3.60	

Executive Engineer
Bruhat Bangalore Mahanagara Palike
Bangalore - 560 053.

Scanned with CamScanner

NO	CHAINAGE Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
	Corner Slab No 133	2	5.40				0.30	3.24	
	Corner Slab No 134	2	5.70				0.30	3.42	
	Corner Slab No 135	2	4.50				0.30	2.70	
	Corner Slab No 136	2	6.60				0.30	3.96	
	Corner Slab No 137	2	5.40				0.30	3.24	
	Corner Slab No 138	2	5.40				0.30	3.24	
	Corner Slab No 139	2	5.70				0.30	3.42	
	Corner Slab No 140	2	7.50				0.30	4.50	
	Corner Slab No 141	2	7.20				0.30	4.32	
	Corner Slab No 142	2	6.00				0.30	3.60	
	Corner Slab No 143	2	5.40				0.30	3.24	
	Corner Slab No 144	2	5.70				0.30	3.42	
	Muthyala Nagara From Under Pass And Surrounding								
	Corner Slab No 1	2	6.00				0.30	3.60	
	Corner Slab No 2	2	5.40				0.30	3.24	
	Corner Slab No 3	2	5.40				0.30	3.24	
	Corner Slab No 4	2	5.70				0.30	3.42	
	Corner Slab No 5	2	6.00				0.30	3.60	
	Corner Slab No 6	2	6.60				0.30	3.96	
	Corner Slab No 7	2	5.40				0.30	3.24	
	Corner Slab No 8	2	6.00				0.30	3.60	
	Corner Slab No 9	2	6.60				0.30	3.96	
	Corner Slab No 10	2	6.60				0.30	3.96	
	Corner Slab No 11	2	6.00				0.30	3.60	
	Corner Slab No 12	2	6.60				0.30	3.96	
	Corner Slab No 13	2	5.70				0.30	3.42	
	Corner Slab No 14	2	6.60				0.30	3.96	
	Corner Slab No 15	2	6.00				0.30	3.60	
	Corner Slab No 16	2	5.40				0.30	3.24	
	Corner Slab No 17	2	5.70				0.30	3.42	
	Corner Slab No 18	2	6.60				0.30	3.96	
	Corner Slab No 19	2	5.40				0.30	3.24	
	Corner Slab No 20	2	6.00				0.30	3.60	
	Corner Slab No 21	2	6.60				0.30	3.96	
	Corner Slab No 22	2	6.00				0.30	3.60	
	Corner Slab No 23	2	6.60				0.30	3.96	
	Corner Slab No 24	2	5.40				0.30	3.24	
	Corner Slab No 25	2	5.70				0.30	3.42	
	Corner Slab No 26	2	5.40				0.30	3.24	
	Corner Slab No 27	2	6.60				0.30	3.96	
	Corner Slab No 28	2	6.60				0.30	3.96	
	Corner Slab No 29	2	6.00				0.30	3.60	
	Corner Slab No 30	2	6.00				0.30	3.60	
	Corner Slab No 31	2	5.40				0.30	3.24	
	Corner Slab No 32	2	5.70				0.30	3.42	
	Corner Slab No 33	2	4.50				0.30	2.70	
	Corner Slab No 34	2	6.60				0.30	3.96	
	Corner Slab No 35	2	5.40				0.30	3.24	
	Corner Slab No 36	2	5.40				0.30	3.24	

Checked
Executive Engineer
Muthyala Nagara Division
Rajarajeshwari Nagara, Mahanagara Palika
Bengaluru - 560 064

Scanned with CamScanner

CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 37	2	5.70				0.30	3.42	
Corner Slab No 38	2	7.50				0.30	4.50	
Corner Slab No 39	2	7.20				0.30	4.32	
Corner Slab No 40	2	6.00				0.30	3.60	
Corner Slab No 41	2	5.40				0.30	3.24	
Corner Slab No 42	2	5.70				0.30	3.42	
Corner Slab No 43	2	6.60				0.30	3.96	
Corner Slab No 44	2	7.50				0.30	4.50	
Corner Slab No 45	2	7.20				0.30	4.32	
Corner Slab No 46	2	5.40				0.30	3.24	
Corner Slab No 47	2	6.00				0.30	3.60	
Corner Slab No 48	2	6.60				0.30	3.96	
Corner Slab No 49	2	6.00				0.30	3.60	
Corner Slab No 50	2	5.40				0.30	3.24	
Corner Slab No 51	2	5.40				0.30	3.24	
Corner Slab No 52	2	5.70				0.30	3.42	
Corner Slab No 53	2	6.00				0.30	3.60	
Corner Slab No 54	2	6.60				0.30	3.96	
Corner Slab No 55	2	5.40				0.30	3.24	
Corner Slab No 56	2	6.00				0.30	3.60	
Corner Slab No 57	2	6.60				0.30	3.96	
Corner Slab No 58	2	6.60				0.30	3.96	
Corner Slab No 59	2	6.00				0.30	3.60	
Corner Slab No 60	2	6.60				0.30	3.96	
Corner Slab No 61	2	5.70				0.30	3.42	
Corner Slab No 62	2	6.60				0.30	3.96	
Corner Slab No 63	2	6.00				0.30	3.60	
Corner Slab No 64	2	5.40				0.30	3.24	
Corner Slab No 65	2	5.70				0.30	3.42	
Corner Slab No 66	2	6.60				0.30	3.96	
Corner Slab No 67	2	5.40				0.30	3.24	
Corner Slab No 68	2	6.00				0.30	3.60	
Corner Slab No 69	2	6.60				0.30	3.96	
Corner Slab No 70	2	6.00				0.30	3.60	
Corner Slab No 71	2	6.60				0.30	3.96	
Corner Slab No 72	2	5.40				0.30	3.24	
Corner Slab No 73	2	5.70				0.30	3.42	
Corner Slab No 74	2	5.40				0.30	3.24	
Corner Slab No 75	2	6.60				0.30	3.96	
Corner Slab No 76	2	6.60				0.30	3.96	
Corner Slab No 77	2	6.00				0.30	3.60	
Corner Slab No 78	2	6.00				0.30	3.60	
Corner Slab No 79	2	5.70				0.30	3.42	
Corner Slab No 80	2	5.40				0.30	3.24	
Corner Slab No 81	2	6.60				0.30	3.96	
Corner Slab No 82	2	6.00				0.30	3.60	
Corner Slab No 83	2	6.00				0.30	3.60	
Corner Slab No 84	2	5.40				0.30	3.24	
Corner Slab No 85	2	5.70				0.30	3.42	
Corner Slab No 86	2	4.50				0.30	2.70	

Engineer, Nagara Division
Mahanagara Palike

Scanned with CamScanner

NO	CHAINAGE Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
	Corner Slab No 87	2	6.60				0.30	3.96	
	Corner Slab No 88	2	5.40				0.30	3.24	
	Corner Slab No 89	2	5.40				0.30	3.24	
	Corner Slab No 90	2	5.70				0.30	3.42	
	Corner Slab No 91	2	7.50				0.30	4.50	
	Corner Slab No 92	2	7.20				0.30	4.32	
	Corner Slab No 93	2	6.00				0.30	3.60	
	Corner Slab No 94	2	5.40				0.30	3.24	
	Corner Slab No 95	2	5.70				0.30	3.42	
	Corner Slab No 96	2	6.60				0.30	3.96	
	Corner Slab No 97	2	7.50				0.30	4.50	
	Corner Slab No 98	2	7.20				0.30	4.32	
	Corner Slab No 99	2	5.40				0.30	3.24	
	Corner Slab No 100	2	6.00				0.30	3.60	
	Corner Slab No 101	2	6.60				0.30	3.96	
	Corner Slab No 102	2	6.00				0.30	3.60	
	Corner Slab No 103	2	5.40				0.30	3.24	
	Corner Slab No 104	2	5.40				0.30	3.24	
	Corner Slab No 105	2	5.70				0.30	3.42	
	Corner Slab No 106	2	6.00				0.30	3.60	
	Corner Slab No 107	2	6.60				0.30	3.96	
	Corner Slab No 108	2	5.40				0.30	3.24	
	Corner Slab No 109	2	6.00				0.30	3.60	
	Corner Slab No 110	2	6.60				0.30	3.96	
	Jahahalli Village								
	Corner Slab No 1	2	6.60						
	Corner Slab No 2	2	6.00				0.30	3.96	
	Corner Slab No 3	2	5.40				0.30	3.60	
	Corner Slab No 4	2	5.70				0.30	3.24	
	Corner Slab No 5	2	6.60				0.30	3.42	
	Corner Slab No 6	2	5.40				0.30	3.96	
	Corner Slab No 7	2	6.00				0.30	3.24	
	Corner Slab No 8	2	6.60				0.30	3.60	
	Corner Slab No 9	2	6.00				0.30	3.96	
	Corner Slab No 10	2	6.60				0.30	3.60	
	Corner Slab No 11	2	5.40				0.30	3.96	
	Corner Slab No 12	2	5.70				0.30	3.24	
	Corner Slab No 13	2	5.40				0.30	3.42	
	Corner Slab No 14	2	6.60				0.30	3.24	
	Corner Slab No 15	2	6.60				0.30	3.96	
	Corner Slab No 16	2	6.00				0.30	3.96	
	Corner Slab No 17	2	6.00				0.30	3.60	
	Corner Slab No 18	2	5.70				0.30	3.60	
	Corner Slab No 19	2	5.40				0.30	3.42	
	Corner Slab No 20	2	6.60				0.30	3.24	
	Corner Slab No 21	2	6.00				0.30	3.96	
	Corner Slab No 22	2	6.60				0.30	3.60	
	Corner Slab No 23	2	5.40				0.30	3.96	
	Corner Slab No 24	2	6.60				0.30	3.24	
	Corner Slab No 25	2	5.70				0.30	3.96	
							0.30	3.42	

Executive Engineer, Project Division, Bangalore Mahanagara Palike

Scanned with CamScanner

CHAINAGE / Land Mark	NO	L (m)	B (m)	BI (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 26	2	5.40				0.30	3.24	
Corner Slab No 27	2	6.00				0.30	3.60	
Corner Slab No 28	2	5.40				0.30	3.24	
Corner Slab No 29	2	5.70				0.30	3.42	
Corner Slab No 30	2	4.50				0.30	2.70	
Corner Slab No 31	2	6.60				0.30	3.96	
Corner Slab No 32	2	5.40				0.30	3.24	
Corner Slab No 33	2	5.40				0.30	3.24	
Corner Slab No 34	2	5.70				0.30	3.42	
Corner Slab No 35	2	7.50				0.30	4.50	
Corner Slab No 36	2	7.20				0.30	4.32	
Corner Slab No 37	2	6.00				0.30	3.60	
Corner Slab No 38	2	5.40				0.30	3.24	
Corner Slab No 39	2	5.70				0.30	3.42	
Corner Slab No 40	2	6.60				0.30	3.96	
Corner Slab No 41	2	7.50				0.30	4.50	
Corner Slab No 42	2	7.20				0.30	4.32	
Corner Slab No 43	2	5.40				0.30	3.24	
Corner Slab No 44	2	6.00				0.30	3.60	
Corner Slab No 45	2	6.60				0.30	3.96	
Corner Slab No 46	2	6.00				0.30	3.60	
Corner Slab No 47	2	5.40				0.30	3.24	
Corner Slab No 48	2	5.40				0.30	3.24	
Corner Slab No 49	2	5.70				0.30	3.42	
Corner Slab No 50	2	6.00				0.30	3.60	
Corner Slab No 51	2	6.60				0.30	3.96	
Corner Slab No 52	2	5.40				0.30	3.24	
Corner Slab No 53	2	6.00				0.30	3.60	
Corner Slab No 54	2	6.60				0.30	3.96	
Corner Slab No 55	2	6.60				0.30	3.96	
Corner Slab No 56	2	6.00				0.30	3.60	
Corner Slab No 57	2	6.60				0.30	3.96	
Corner Slab No 58	2	5.70				0.30	3.42	
Corner Slab No 59	2	6.60				0.30	3.96	
Corner Slab No 60	2	6.00				0.30	3.60	
Corner Slab No 61	2	5.40				0.30	3.24	
Corner Slab No 62	2	5.70				0.30	3.42	
Corner Slab No 63	2	6.60				0.30	3.96	
Corner Slab No 64	2	5.40				0.30	3.24	
Corner Slab No 65	2	6.00				0.30	3.60	
Corner Slab No 66	2	6.60				0.30	3.96	
Corner Slab No 67	2	6.00				0.30	3.60	
Corner Slab No 68	2	6.60				0.30	3.96	
Corner Slab No 69	2	5.40				0.30	3.24	
Corner Slab No 70	2	5.70				0.30	3.42	
Corner Slab No 71	2	5.40				0.30	3.24	
Corner Slab No 72	2	6.60				0.30	3.96	
Corner Slab No 73	2	6.60				0.30	3.96	
Corner Slab No 74	2	6.00				0.30	3.60	

Engineer
Kalutara Nagara Division
Kalutara Municipal Council

Scanned with CamScanner

CHAINAGE / Land Mark	NO	L. (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 75	2	6.00				0.30	3.60	
Corner Slab No 76	2	5.70				0.30	3.42	
Corner Slab No 77	2	5.40				0.30	3.24	
Corner Slab No 78	2	6.00				0.30	3.60	
Corner Slab No 79	2	6.60				0.30	3.96	
Corner Slab No 80	2	6.00				0.30	3.60	
Corner Slab No 81	2	6.60				0.30	3.96	
Corner Slab No 82	2	5.40				0.30	3.24	
Corner Slab No 83	2	5.70				0.30	3.42	
Corner Slab No 84	2	5.40				0.30	3.24	
Corner Slab No 85	2	6.60				0.30	3.96	
Corner Slab No 86	2	6.00				0.30	3.60	
Corner Slab No 87	2	6.60				0.30	3.96	
Corner Slab No 88	2	6.00				0.30	3.60	
Corner Slab No 89	2	6.60				0.30	3.96	
Corner Slab No 90	2	5.40				0.30	3.24	
Corner Slab No 91	2	5.70				0.30	3.42	
Corner Slab No 92	2	5.40				0.30	3.24	
Corner Slab No 93	2	6.60				0.30	3.96	
Corner Slab No 94	2	6.60				0.30	3.96	
Corner Slab No 95	2	6.00				0.30	3.60	
Corner Slab No 96	2	6.00				0.30	3.60	
Corner Slab No 97	2	6.60				0.30	3.96	
Corner Slab No 98	2	6.00				0.30	3.60	
Corner Slab No 99	2	6.60				0.30	3.96	
Corner Slab No 100	2	5.40				0.30	3.24	
Corner Slab No 101	2	5.70				0.30	3.42	
Corner Slab No 102	2	5.40				0.30	3.24	
Corner Slab No 103	2	6.60				0.30	3.96	
Corner Slab No 104	2	6.00				0.30	3.60	
Corner Slab No 105	2	6.60				0.30	3.96	
Corner Slab No 106	2	6.00				0.30	3.60	
Corner Slab No 107	2	6.60				0.30	3.96	
Corner Slab No 108	2	5.40				0.30	3.24	
Corner Slab No 109	2	5.70				0.30	3.42	
Corner Slab No 110	2	5.40				0.30	3.24	
Corner Slab No 111	2	6.60				0.30	3.96	
Corner Slab No 112	2	6.60				0.30	3.96	
Corner Slab No 113	2	6.00				0.30	3.60	
Corner Slab No 114	2	6.00				0.30	3.60	
Corner Slab No 115	2	5.70				0.30	3.42	
Corner Slab No 116	2	5.40				0.30	3.24	
Corner Slab No 117	2	6.00				0.30	3.60	
Corner Slab No 118	2	6.60				0.30	3.96	
Corner Slab No 119	2	6.00				0.30	3.60	
Corner Slab No 120	2	6.60				0.30	3.96	
Corner Slab No 121	2	5.40				0.30	3.24	
Corner Slab No 122	2	5.70				0.30	3.42	
Corner Slab No 123	2	5.40				0.30	3.24	
Corner Slab No 124	2	6.60				0.30	3.96	

Executive Engineer
Kandy Kandy Nagara Division
Kandy Nagara Palike
Kandy

Scanned with CamScanner

CHAINAGE / Land Mark	NO	L (m)	B (m)	Bl (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 125	2	6.60				0.30	3.96	
Ward No 37								
Corner Slab No 1	2	6.84				0.30	4.10	
Corner Slab No 2	2	7.22				0.30	4.33	
Corner Slab No 3	2	6.84				0.30	4.10	
Corner Slab No 4	2	8.36				0.30	5.02	
Corner Slab No 5	2	8.36				0.30	5.02	
Corner Slab No 6	2	7.60				0.30	4.56	
Corner Slab No 7	2	7.60				0.30	4.56	
Corner Slab No 8	2	7.22				0.30	4.33	
Corner Slab No 9	2	8.36				0.30	5.02	
Corner Slab No 10	2	6.84				0.30	4.10	
Corner Slab No 11	2	7.22				0.30	4.33	
Corner Slab No 12	2	6.84				0.30	4.10	
Corner Slab No 13	2	8.36				0.30	5.02	
Corner Slab No 14	2	8.36				0.30	5.02	
Corner Slab No 15	2	7.60				0.30	4.56	
Corner Slab No 16	2	7.60				0.30	4.56	
Corner Slab No 17	2	7.22				0.30	4.33	
Corner Slab No 18	2	6.84				0.30	4.10	
Corner Slab No 19	2	7.60				0.30	4.56	
Corner Slab No 20	2	8.36				0.30	5.02	
Corner Slab No 21	2	7.60				0.30	4.56	
Corner Slab No 22	2	8.36				0.30	5.02	
Corner Slab No 23	2	6.84				0.30	4.10	
Corner Slab No 24	2	7.22				0.30	4.33	
Corner Slab No 25	2	6.84				0.30	4.10	
Corner Slab No 26	2	8.36				0.30	5.02	
Corner Slab No 27	2	8.36				0.30	5.02	
Corner Slab No 28	2	7.60				0.30	4.56	
Corner Slab No 29	2	7.60				0.30	4.56	
Corner Slab No 30	2	8.36				0.30	5.02	
Corner Slab No 31	2	6.84				0.30	4.10	
Corner Slab No 32	2	7.22				0.30	4.33	
Corner Slab No 33	2	6.84				0.30	4.10	
Corner Slab No 34	2	8.36				0.30	5.02	
Corner Slab No 35	2	8.36				0.30	5.02	
Corner Slab No 36	2	7.60				0.30	4.56	
Corner Slab No 37	2	7.60				0.30	4.56	
Corner Slab No 38	2	7.22				0.30	4.33	
Corner Slab No 39	2	6.84				0.30	4.10	
Corner Slab No 40	2	7.60				0.30	4.56	
Corner Slab No 41	2	8.36				0.30	5.02	
Corner Slab No 42	2	7.60				0.30	4.56	
Corner Slab No 43	2	8.36				0.30	5.02	
Corner Slab No 44	2	6.84				0.30	4.10	
Corner Slab No 45	2	7.22				0.30	4.33	
Corner Slab No 46	2	6.84				0.30	4.10	
Corner Slab No 47	2	8.36				0.30	5.02	

Executive Engineer
Executive Engineer Anegudi Division
Belgaum Mahanagara Palike
Belgaum - 590 054.

Scanned with CamScanner

CHAINAGE / Land Mark	NO	L (m)	B (m)	Bl (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 48	2	8.36				0.30	5.02	
Corner Slab No 49	2	8.36				0.30	5.02	
Corner Slab No 50	2	6.84				0.30	4.10	
Corner Slab No 51	2	7.22				0.30	4.33	
Corner Slab No 52	2	6.84				0.30	4.10	
Corner Slab No 53	2	8.36				0.30	5.02	
Corner Slab No 54	2	8.36				0.30	5.02	
Corner Slab No 55	2	7.60				0.30	4.56	
Corner Slab No 56	2	7.60				0.30	4.56	
Corner Slab No 57	2	7.22				0.30	4.33	
Corner Slab No 58	2	6.84				0.30	4.10	
Corner Slab No 59	2	7.60				0.30	4.56	
Corner Slab No 60	2	8.36				0.30	5.02	
Corner Slab No 61	2	7.60				0.30	4.56	
Corner Slab No 62	2	8.36				0.30	5.02	
Corner Slab No 63	2	6.84				0.30	4.10	
Corner Slab No 64	2	7.22				0.30	4.33	
Corner Slab No 65	2	6.84				0.30	4.10	
Corner Slab No 66	2	8.36				0.30	5.02	
Corner Slab No 67	2	8.36				0.30	5.02	
Corner Slab No 68	2	7.60				0.30	4.56	
Corner Slab No 69	2	7.60				0.30	4.56	
Corner Slab No 70	2	7.22				0.30	4.33	
Corner Slab No 71	2	6.84				0.30	4.10	
Corner Slab No 72	2	8.36				0.30	5.02	
Corner Slab No 73	2	6.84				0.30	4.10	
Corner Slab No 74	2	7.22				0.30	4.33	
Corner Slab No 75	2	6.84				0.30	4.10	
Corner Slab No 76	2	8.36				0.30	5.02	
Corner Slab No 77	2	8.36				0.30	5.02	
Corner Slab No 78	2	7.60				0.30	4.56	
Corner Slab No 79	2	7.60				0.30	4.56	
Corner Slab No 80	2	7.22				0.30	4.33	
Corner Slab No 81	2	6.84				0.30	4.10	
Corner Slab No 82	2	7.60				0.30	4.56	
Corner Slab No 83	2	8.36				0.30	5.02	
Corner Slab No 84	2	7.60				0.30	4.56	
Corner Slab No 85	2	8.36				0.30	5.02	
Corner Slab No 86	2	6.84				0.30	4.10	
Corner Slab No 87	2	7.22				0.30	4.33	
Corner Slab No 88	2	6.84				0.30	4.10	
Corner Slab No 89	2	8.36				0.30	5.02	
Corner Slab No 90	2	8.36				0.30	5.02	
Corner Slab No 91	2	6.84				0.30	4.10	
Corner Slab No 92	2	7.22				0.30	4.33	
Corner Slab No 93	2	6.84				0.30	4.10	
Corner Slab No 94	2	8.36				0.30	5.02	
Corner Slab No 95	2	8.36				0.30	5.02	
Corner Slab No 96	2	7.60				0.30	4.56	
Corner Slab No 97	2	7.60				0.30	4.56	

Executive Engineer
Uduwari Nagara Division
Pradeshiya Mahanagara Palika
Kandy.

Scanned with CamScanner

CHAINAGE / Land Mark	NO	L (m)	B (m)	BI (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 98	2	7.22				0.30	4.33	
Corner Slab No 99	2	6.84				0.30	4.10	
Corner Slab No 100	2	7.60				0.30	4.56	
Corner Slab No 101	2	8.36				0.30	5.02	
Corner Slab No 102	2	7.60				0.30	4.56	
Corner Slab No 103	2	8.36				0.30	5.02	
Corner Slab No 104	2	6.84				0.30	4.10	
Corner Slab No 105	2	7.22				0.30	4.33	
Corner Slab No 106	2	6.84				0.30	4.10	
Corner Slab No 107	2	8.36				0.30	5.02	
Corner Slab No 108	2	8.36				0.30	5.02	
Corner Slab No 109	2	7.60				0.30	4.56	
Corner Slab No 110	2	7.60				0.30	4.56	
Corner Slab No 111	2	7.22				0.30	4.33	
Corner Slab No 112	2	8.36				0.30	5.02	
Corner Slab No 113	2	6.84				0.30	4.10	
Corner Slab No 114	2	7.22				0.30	4.33	
Corner Slab No 115	2	6.84				0.30	4.10	
Corner Slab No 116	2	8.36				0.30	5.02	
Corner Slab No 117	2	8.36				0.30	5.02	
Corner Slab No 118	2	7.60				0.30	4.56	
Corner Slab No 119	2	7.60				0.30	4.56	
Corner Slab No 120	2	7.22				0.30	4.33	
Corner Slab No 121	2	6.84				0.30	4.10	
Corner Slab No 122	2	7.60				0.30	4.56	
Corner Slab No 123	2	8.36				0.30	5.02	
Corner Slab No 124	2	7.60				0.30	4.56	
Corner Slab No 125	2	8.36				0.30	5.02	
Corner Slab No 126	2	6.84				0.30	4.10	
Corner Slab No 127	2	7.22				0.30	4.33	
Corner Slab No 128	2	6.84				0.30	4.10	
Corner Slab No 129	2	8.36				0.30	5.02	
Corner Slab No 130	2	8.36				0.30	5.02	
Corner Slab No 131	2	7.60				0.30	4.56	
Corner Slab No 132	2	8.36				0.30	5.02	
Corner Slab No 133	2	6.84				0.30	4.10	
Corner Slab No 134	2	6.08				0.30	3.65	
Corner Slab No 135	2	5.76				0.30	3.46	
Corner Slab No 136	2	7.04				0.30	4.22	
Corner Slab No 137	2	7.04				0.30	4.22	
Corner Slab No 138	2	6.40				0.30	3.84	
Corner Slab No 139	2	6.40				0.30	3.84	
Corner Slab No 140	2	6.08				0.30	3.65	
Corner Slab No 141	2	5.76				0.30	3.46	
Corner Slab No 142	2	6.40				0.30	3.84	
Corner Slab No 143	2	7.04				0.30	4.22	
Corner Slab No 144	2	6.40				0.30	3.84	
Corner Slab No 145	2	7.04				0.30	4.22	
Corner Slab No 146	2	5.76				0.30	3.46	
Corner Slab No 147	2	6.08				0.30	3.65	

Executive Engineer
Mangalore Tropical Division
Palike Mahanagara Palike
Mangalore - 575 004.

Scanned with CamScanner

CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 148	2	5.76				0.30	3.46	
Corner Slab No 149	2	7.04				0.30	4.22	
Corner Slab No 150	2	7.04				0.30	4.22	
Corner Slab No 151	2	6.40				0.30	3.84	
Corner Slab No 152	2	6.40				0.30	3.84	
Corner Slab No 153	2	6.08				0.30	3.65	
Corner Slab No 154	2	7.04				0.30	4.22	
Corner Slab No 155	2	5.76				0.30	3.46	
Corner Slab No 156	2	6.08				0.30	3.65	
Corner Slab No 157	2	5.76				0.30	3.46	
Corner Slab No 158	2	7.04				0.30	4.22	
Corner Slab No 159	2	7.04				0.30	4.22	
Corner Slab No 160	2	6.40				0.30	3.84	
Corner Slab No 161	2	6.40				0.30	3.84	
Corner Slab No 162	2	6.08				0.30	3.65	
Corner Slab No 163	2	5.76				0.30	3.46	
Corner Slab No 164	2	6.40				0.30	3.84	
Corner Slab No 165	2	7.04				0.30	4.22	
Corner Slab No 166	2	6.40				0.30	3.84	
Corner Slab No 167	2	7.04				0.30	4.22	
Corner Slab No 168	2	5.76				0.30	3.46	
Corner Slab No 169	2	6.08				0.30	3.65	
Corner Slab No 170	2	5.76				0.30	3.46	
Corner Slab No 171	2	7.04				0.30	4.22	
Corner Slab No 172	2	7.04				0.30	4.22	
Corner Slab No 173	2	6.40				0.30	3.84	
Corner Slab No 174	2	6.40				0.30	3.84	
Corner Slab No 175	2	6.08				0.30	3.65	
Corner Slab No 176	2	7.04				0.30	4.22	
Corner Slab No 177	2	5.76				0.30	3.46	
Corner Slab No 178	2	6.08				0.30	3.65	
Corner Slab No 179	2	5.76				0.30	3.46	
Corner Slab No 180	2	7.04				0.30	4.22	
Corner Slab No 181	2	7.04				0.30	4.22	
Corner Slab No 182	2	6.40				0.30	3.84	
Corner Slab No 183	2	6.40				0.30	3.84	
Corner Slab No 184	2	6.08				0.30	3.65	
Corner Slab No 185	2	5.76				0.30	3.46	
Corner Slab No 186	2	6.40				0.30	3.84	
Corner Slab No 187	2	7.04				0.30	4.22	
Corner Slab No 188	2	6.40				0.30	3.84	
Corner Slab No 189	2	7.04				0.30	4.22	
Corner Slab No 190	2	5.76				0.30	3.46	
Corner Slab No 191	2	6.08				0.30	3.65	
Corner Slab No 192	2	5.76				0.30	3.46	
Corner Slab No 193	2	7.04				0.30	4.22	
Corner Slab No 194	2	7.04				0.30	4.22	
Corner Slab No 195	2	7.04				0.30	4.22	
Corner Slab No 196	2	5.76				0.30	3.46	
Corner Slab No 197	2	6.08				0.30	3.65	

Scanned with CamScanner

CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 198	2	5.76				0.30	3.46	
Corner Slab No 199	2	7.04				0.30	4.22	
Corner Slab No 200	2	7.04				0.30	4.22	
Corner Slab No 201	2	6.40				0.30	3.84	
Corner Slab No 202	2	6.40				0.30	3.84	
Corner Slab No 203	2	6.08				0.30	3.65	
Corner Slab No 204	2	5.76				0.30	3.46	
Corner Slab No 205	2	6.40				0.30	3.84	
Ward No 17		**FOR NEW KERBS**						
Sundar Nagar								
Corner Slab No 1	2	3.66						
Corner Slab No 2	2	3.29						
Corner Slab No 3	2	3.48				0.30	2.20	
Corner Slab No 4	2	2.75				0.30	1.98	
Corner Slab No 5	2	4.03				0.30	2.09	
Corner Slab No 6	2	3.29				0.30	1.65	
Corner Slab No 7	2	3.29				0.30	2.42	
Corner Slab No 8	2	3.48				0.30	1.98	
Corner Slab No 9	2	4.58				0.30	1.98	
Corner Slab No 10	2	4.39				0.30	2.09	
Corner Slab No 11	2	3.66				0.30	2.75	
Corner Slab No 12	2	3.29				0.30	2.64	
Corner Slab No 13	2	3.48				0.30	2.20	
Corner Slab No 14	2	4.03				0.30	1.98	
Corner Slab No 15	2	4.58				0.30	2.09	
Corner Slab No 16	2	4.39				0.30	2.42	
Corner Slab No 17	2	3.29				0.30	2.75	
Corner Slab No 18	2	3.66				0.30	2.64	
Corner Slab No 19	2	4.03				0.30	1.98	
Corner Slab No 20	2	3.66				0.30	2.20	
Corner Slab No 21	2	3.29				0.30	2.42	
Corner Slab No 22	2	3.29				0.30	2.20	
Corner Slab No 23	2	3.48				0.30	1.98	
Corner Slab No 24	2	3.66				0.30	1.98	
Corner Slab No 25	2	4.03				0.30	2.09	
Corner Slab No 26	2	3.29				0.30	2.20	
Corner Slab No 27	2	3.66				0.30	2.42	
Corner Slab No 28	2	4.03				0.30	1.98	
Corner Slab No 29	2	4.03				0.30	2.20	
Corner Slab No 30	2	3.66				0.30	2.42	
Corner Slab No 31	2	4.03				0.30	2.42	
Corner Slab No 32	2	3.48				0.30	2.20	
Corner Slab No 33	2	4.03				0.30	2.09	
Corner Slab No 34	2	3.66				0.30	2.42	
Corner Slab No 35	2	3.29				0.30	2.20	
Corner Slab No 36	2	3.48				0.30	1.98	
Corner Slab No 37	2	4.03				0.30	2.09	
Corner Slab No 38	2	3.29				0.30	2.42	
						0.30	1.98	

Scanned with CamScanner

CHAINAGE Land Mark	NO	L (m)	B (m)	Bl (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 39	2	3.66				0.30	2.20	
Corner Slab No 40	2	4.03				0.30	2.42	
Corner Slab No 41	2	3.66				0.30	2.20	
Corner Slab No 42	2	4.03				0.30	2.42	
Corner Slab No 43	2	3.29				0.30	1.98	
Corner Slab No 44	2	3.48				0.30	2.09	
Corner Slab No 45	2	3.29				0.30	1.98	
Corner Slab No 46	2	4.03				0.30	2.42	
Corner Slab No 47	2	4.03				0.30	2.42	
Corner Slab No 48	2	3.66				0.30	2.20	
Corner Slab No 49	2	3.66				0.30	2.20	
Corner Slab No 50	2	3.48				0.30	2.09	
Corner Slab No 51	2	3.29				0.30	1.98	
Corner Slab No 52	2	4.03				0.30	2.42	
Corner Slab No 53	2	3.66				0.30	2.20	
Corner Slab No 54	2	4.03				0.30	2.42	
Corner Slab No 55	2	3.29				0.30	1.98	
Corner Slab No 56	2	4.03				0.30	2.42	
Corner Slab No 57	2	3.48				0.30	2.09	
Corner Slab No 58	2	3.29				0.30	1.98	
Gokulam Grand And Mathikere Signals surrounding								
Corner Slab No 1	2	3.66				0.30	2.20	
Corner Slab No 2	2	3.29				0.30	1.98	
Corner Slab No 3	2	3.48				0.30	2.09	
Corner Slab No 4	2	2.75				0.30	1.65	
Corner Slab No 5	2	4.03				0.30	2.42	
Corner Slab No 6	2	3.29				0.30	1.98	
Corner Slab No 7	2	3.29				0.30	1.98	
Corner Slab No 8	2	3.48				0.30	2.09	
Corner Slab No 9	2	4.58				0.30	2.75	
Corner Slab No 10						0.30	0.00	
Corner Slab No 11	2	3.66				0.30	2.20	
Corner Slab No 12	2	3.29				0.30	1.98	
Corner Slab No 13	2	3.48				0.30	2.09	
Corner Slab No 14	2	4.03				0.30	2.42	
Corner Slab No 15	2	4.58				0.30	2.75	
Corner Slab No 16	2	4.39				0.30	2.64	
Corner Slab No 17	2	3.29				0.30	1.98	
Corner Slab No 18	2	3.66				0.30	2.20	
Corner Slab No 19	2	4.03				0.30	2.42	
Corner Slab No 20	2	3.66				0.30	2.20	
Corner Slab No 21	2	3.29				0.30	1.98	
Corner Slab No 22	2	3.29				0.30	1.98	
Corner Slab No 23	2	3.48				0.30	2.09	
Corner Slab No 24	2	3.66				0.30	2.20	
Corner Slab No 25	2	4.03				0.30	2.42	
Corner Slab No 26	2	3.29				0.30	1.98	
Corner Slab No 27	2	3.66				0.30	2.20	
Corner Slab No 28	2	4.03				0.30	2.42	

Scanned with CamScanner

CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 29	2	4.03				0.30	2.42	
Corner Slab No 30	2	3.66				0.30	2.20	
Corner Slab No 31	2	4.03				0.30	2.42	
Corner Slab No 32	2	3.48				0.30	2.09	
Corner Slab No 33	2	4.03				0.30	2.42	
Corner Slab No 34	2	3.66				0.30	2.20	
Corner Slab No 35	2	3.29				0.30	1.98	
Corner Slab No 36	2	3.48				0.30	2.09	
Corner Slab No 37	2	4.03				0.30	2.42	
Corner Slab No 38	2	3.29				0.30	1.98	
Corner Slab No 39	2	3.66				0.30	2.20	
Corner Slab No 40	2	4.03				0.30	2.42	
Corner Slab No 41	2	3.66				0.30	2.20	
Corner Slab No 42	2	4.03				0.30	2.42	
Corner Slab No 43	2	3.29				0.30	1.98	
Corner Slab No 44	2	3.48				0.30	2.09	
Corner Slab No 45	2	3.66				0.30	2.20	
Corner Slab No 46	2	3.29				0.30	1.98	
Corner Slab No 47	2	3.48				0.30	2.09	
Corner Slab No 48	2	2.75				0.30	1.65	
Corner Slab No 49	2	4.03				0.30	2.42	
Corner Slab No 50	2	3.29				0.30	1.98	
Corner Slab No 51	2	3.29				0.30	1.98	
Corner Slab No 52	2	3.48				0.30	2.09	
Corner Slab No 53	2	4.58				0.30	2.75	
Corner Slab No 54	2	4.39				0.30	2.64	
Corner Slab No 55	2	3.66				0.30	2.20	
Corner Slab No 56	2	3.29				0.30	1.98	
Corner Slab No 57	2	3.48				0.30	2.09	
Corner Slab No 58	2	4.03				0.30	2.42	
Corner Slab No 59	2	4.58				0.30	2.75	
Corner Slab No 60	2	4.39				0.30	2.64	
Corner Slab No 61	2	3.29				0.30	1.98	
Corner Slab No 62	2	3.66				0.30	2.20	
Corner Slab No 63	2	4.03				0.30	2.42	
Corner Slab No 64	2	3.66				0.30	2.20	
Corner Slab No 65	2	3.29				0.30	1.98	
Corner Slab No 66	2	3.29				0.30	1.98	
Corner Slab No 67	2	3.48				0.30	2.09	
Corner Slab No 68	2	3.66				0.30	2.20	
Corner Slab No 69	2	4.03				0.30	2.42	
Corner Slab No 70	2	3.29				0.30	1.98	
Corner Slab No 71	2	3.66				0.30	2.20	
Corner Slab No 72	2	4.03				0.30	2.42	
Corner Slab No 73	2	4.03				0.30	2.42	
Corner Slab No 74	2	3.66				0.30	2.20	
Corner Slab No 75	2	4.03				0.30	2.42	
Corner Slab No 76	2	3.48				0.30	2.09	
Corner Slab No 77	2	4.03				0.30	2.42	

Executive Engineer, Apparel Division
Karnataka Handicrafts Dev. Corp. Ltd.
Bangalore - 560 064.

Scanned with CamScanner

CHAINAGE Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 78	2	3.66				0.30	2.20	
Corner Slab No 79	2	3.29				0.30	1.98	
Corner Slab No 80	2	3.48				0.30	2.09	
Corner Slab No 81	2	4.03				0.30	2.42	
Corner Slab No 82	2	3.29				0.30	1.98	
Corner Slab No 83	2	3.66				0.30	2.20	
Corner Slab No 84	2	4.03				0.30	2.42	
Corner Slab No 85	2	3.66				0.30	2.20	
Corner Slab No 86	2	4.03				0.30	2.42	
Corner Slab No 87	2	3.29				0.30	1.98	
Corner Slab No 88	2	3.48				0.30	2.09	
Corner Slab No 89	2	3.29				0.30	1.98	
Corner Slab No 90	2	4.03				0.30	2.42	
Corner Slab No 91	2	4.03				0.30	2.42	
Corner Slab No 92	2	3.66				0.30	2.20	
Corner Slab No 93	2	3.66				0.30	2.20	
Corner Slab No 94	2	3.48				0.30	2.09	
Corner Slab No 95	2	3.29				0.30	1.98	
Corner Slab No 96	2	4.03				0.30	2.42	
Corner Slab No 97	2	3.66				0.30	2.20	
Corner Slab No 98	2	4.03				0.30	2.42	
Corner Slab No 99	2	3.29				0.30	1.98	
Corner Slab No 100	2	3.66				0.30	2.20	
Corner Slab No 101	2	3.29				0.30	1.98	
Corner Slab No 102	2	3.48				0.30	2.09	
Corner Slab No 103	2	2.75				0.30	1.65	
Corner Slab No 104	2	4.03				0.30	2.42	
Corner Slab No 105	2	3.29				0.30	1.98	
Corner Slab No 106	2	3.29				0.30	1.98	
Corner Slab No 107	2	3.48				0.30	2.09	
Corner Slab No 108	2	4.58				0.30	2.75	
Corner Slab No 109	2	4.39				0.30	2.64	
Corner Slab No 110	2	3.66				0.30	2.20	
Corner Slab No 111	2	3.29				0.30	1.98	
Corner Slab No 112	2	3.48				0.30	2.09	
Corner Slab No 113	2	4.03				0.30	2.42	
Corner Slab No 114	2	4.58				0.30	2.75	
Corner Slab No 115	2	4.39				0.30	2.64	
Corner Slab No 116	2	3.29				0.30	1.98	
Corner Slab No 117	2	3.66				0.30	2.20	
Corner Slab No 118	2	4.03				0.30	2.42	
Corner Slab No 119	2	3.66				0.30	2.20	
Corner Slab No 120	2	3.29				0.30	1.98	
Corner Slab No 121	2	3.29				0.30	1.98	
Corner Slab No 122	2	3.48				0.30	2.09	
Corner Slab No 123	2	3.66				0.30	2.20	
Corner Slab No 124	2	4.03				0.30	2.42	
Corner Slab No 125	2	3.29				0.30	1.98	
Corner Slab No 126	2	3.66				0.30	2.20	
Corner Slab No 127	2	4.03				0.30	2.42	

Scanned with CamScanner

CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 128	2	4.03				0.30	2.42	
Corner Slab No 129	2	3.66				0.30	2.20	
Corner Slab No 130	2	4.03				0.30	2.42	
Corner Slab No 131	2	3.48				0.30	2.09	
Corner Slab No 132	2	4.03				0.30	2.42	
Corner Slab No 133	2	3.66				0.30	2.20	
Corner Slab No 134	2	3.29				0.30	1.98	
Corner Slab No 135	2	3.48				0.30	2.09	
Corner Slab No 136	2	4.03				0.30	2.42	
Corner Slab No 137	2	3.29				0.30	1.98	
Corner Slab No 138	2	3.66				0.30	2.20	
Corner Slab No 139	2	4.03				0.30	2.42	
Corner Slab No 140	2	3.66				0.30	2.20	
Corner Slab No 141	2	4.03				0.30	2.42	
Corner Slab No 142	2	3.29				0.30	1.98	
Corner Slab No 143	2	3.48				0.30	2.09	
Corner Slab No 144	2	3.29				0.30	1.98	
Corner Slab No 145	2	4.03				0.30	2.42	
Corner Slab No 146	2	4.03				0.30	2.42	
Corner Slab No 147	2	3.66				0.30	2.20	
Corner Slab No 148	2	3.66				0.30	2.20	
Corner Slab No 149	2	3.29				0.30	1.98	
Corner Slab No 150	2	3.48				0.30	2.09	
Corner Slab No 151	2	2.75				0.30	1.65	
Corner Slab No 152	2	4.03				0.30	2.42	
Corner Slab No 153	2	3.29				0.30	1.98	
Corner Slab No 154	2	3.29				0.30	1.98	
Corner Slab No 155	2	3.48				0.30	2.09	
Mathikere Signal And Ganesha Ground								
Corner Slab No 1	2	4.39				0.30	2.64	
Corner Slab No 2	2	3.66				0.30	2.20	
Corner Slab No 3	2	3.29				0.30	1.98	
Corner Slab No 4	2	3.48				0.30	2.09	
Corner Slab No 5	2	4.03				0.30	2.42	
Corner Slab No 6	2	4.58				0.30	2.75	
Corner Slab No 7	2	4.39				0.30	2.64	
Corner Slab No 8	2	3.29				0.30	1.98	
Corner Slab No 9	2	3.66				0.30	2.20	
Corner Slab No 10	2	4.03				0.30	2.42	
Corner Slab No 11	2	3.66				0.30	2.20	
Corner Slab No 12	2	3.29				0.30	1.98	
Corner Slab No 13	2	3.29				0.30	1.98	
Corner Slab No 14	2	3.48				0.30	2.09	
Corner Slab No 15	2	3.66				0.30	2.20	
Corner Slab No 16	2	4.03				0.30	2.42	
Corner Slab No 17	2	3.29				0.30	1.98	
Corner Slab No 18	2	3.66				0.30	2.20	
Corner Slab No 19	2	4.03				0.30	2.42	
Corner Slab No 20	2	4.03				0.30	2.42	
Corner Slab No 21	2	3.66				0.30	2.20	

Scanned with CamScanner

CHAINAGE / Land Mark	NO	L (m)	B (m)	Bl (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 22	2	4.03				0.30	2.42	
Corner Slab No 23	2	3.48				0.30	2.09	
Corner Slab No 24	2	4.03				0.30	2.42	
Corner Slab No 25	2	3.66				0.30	2.20	
Corner Slab No 26	2	3.29				0.30	1.98	
Corner Slab No 27	2	3.48				0.30	2.09	
Corner Slab No 28	2	4.03				0.30	2.42	
Corner Slab No 29	2	3.29				0.30	1.98	
Corner Slab No 30	2	3.66				0.30	2.20	
Corner Slab No 31	2	4.03				0.30	2.42	
Corner Slab No 32	2	3.66				0.30	2.20	
Corner Slab No 33	2	4.03				0.30	2.42	
Corner Slab No 34	2	3.29				0.30	1.98	
Corner Slab No 35	2	3.48				0.30	2.09	
Corner Slab No 36	2	3.29				0.30	1.98	
Corner Slab No 37	2	4.03				0.30	2.42	
Corner Slab No 38	2	4.03				0.30	2.42	
Corner Slab No 39	2	3.66				0.30	2.20	
Corner Slab No 40	2	3.66				0.30	2.20	
Corner Slab No 41	2	3.48				0.30	2.09	
Corner Slab No 42	2	3.29				0.30	1.98	
Corner Slab No 43	2	4.03				0.30	2.42	
Corner Slab No 44	2	3.66				0.30	2.20	
Corner Slab No 45	2	4.03				0.30	2.42	
Corner Slab No 46	2	3.66				0.30	2.20	
Corner Slab No 47	2	3.29				0.30	1.98	
Corner Slab No 48	2	3.48				0.30	2.09	
Corner Slab No 49	2	2.75				0.30	1.65	
Corner Slab No 50	2	4.03				0.30	2.42	
Corner Slab No 51	2	3.29				0.30	1.98	
Corner Slab No 52	2	3.29				0.30	1.98	
Corner Slab No 53	2	3.48				0.30	2.09	
Corner Slab No 54	2	4.58				0.30	2.75	
Corner Slab No 55	2	4.39				0.30	2.64	
Corner Slab No 56	2	3.66				0.30	2.20	
Corner Slab No 57	2	3.29				0.30	1.98	
Corner Slab No 58	2	3.48				0.30	2.09	
Corner Slab No 59	2	4.03				0.30	2.42	
Corner Slab No 60	2	4.58				0.30	2.75	
Corner Slab No 61	2	4.39				0.30	2.64	
Corner Slab No 62	2	3.29				0.30	1.98	
Corner Slab No 63	2	3.66				0.30	2.20	
Corner Slab No 64	2	4.03				0.30	2.42	
Corner Slab No 65	2	3.66				0.30	2.20	
Corner Slab No 66	2	3.29				0.30	1.98	
Corner Slab No 67	2	3.29				0.30	1.98	
Corner Slab No 68	2	3.48				0.30	2.09	
Corner Slab No 69	2	3.66				0.30	2.20	
Corner Slab No 70	2	4.03				0.30	2.42	

Scanned with CamScanner

CHAINAGE Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 71	2	3.29				0.30	1.98	
Corner Slab No 72	2	3.66				0.30	2.20	
Corner Slab No 73	2	4.03				0.30	2.42	
Corner Slab No 74	2	4.03				0.30	2.42	
Corner Slab No 75	2	3.66				0.30	2.20	
Corner Slab No 76	2	4.03				0.30	2.42	
Corner Slab No 77	2	3.48				0.30	2.09	
Corner Slab No 78	2	4.03				0.30	2.42	
Corner Slab No 79	2	3.66				0.30	2.20	
Corner Slab No 80	2	3.29				0.30	1.98	
Corner Slab No 81	2	3.48				0.30	2.09	
Corner Slab No 82	2	4.03				0.30	2.42	
Corner Slab No 83	2	3.29				0.30	1.98	
Corner Slab No 84	2	3.66				0.30	2.20	
Corner Slab No 85	2	4.03				0.30	2.42	
Corner Slab No 86	2	3.66				0.30	2.20	
Corner Slab No 87	2	4.03				0.30	2.42	
Corner Slab No 88	2	3.29				0.30	1.98	
Corner Slab No 89	2	3.48				0.30	2.09	
Corner Slab No 90	2	3.29				0.30	1.98	
Corner Slab No 91	2	4.03				0.30	2.42	
Corner Slab No 92	2	4.03				0.30	2.42	
Corner Slab No 93	2	3.66				0.30	2.20	
Corner Slab No 94	2	3.66				0.30	2.20	
Corner Slab No 95	2	3.29				0.30	1.98	
Corner Slab No 96	2	3.48				0.30	2.09	
Corner Slab No 97	2	2.75				0.30	1.65	
Corner Slab No 98	2	4.03				0.30	2.42	
Corner Slab No 99	2	3.29				0.30	1.98	
Corner Slab No 100	2	3.29				0.30	1.98	
Corner Slab No 101	2	3.48				0.30	2.09	
Corner Slab No 102	2	4.58				0.30	2.75	
Corner Slab No 103	2	4.39				0.30	2.64	
Corner Slab No 104	2	3.66				0.30	2.20	
Corner Slab No 105	2	3.29				0.30	1.98	
Corner Slab No 106	2	3.48				0.30	2.09	
Corner Slab No 107	2	4.03				0.30	2.42	
Corner Slab No 108	2	4.58				0.30	2.75	
Corner Slab No 109	2	4.39				0.30	2.64	
Corner Slab No 110	2	3.29				0.30	1.98	
Corner Slab No 111	2	3.66				0.30	2.20	
Corner Slab No 112	2	4.03				0.30	2.42	
Corner Slab No 113	2	3.66				0.30	2.20	
Corner Slab No 114	2	3.29				0.30	1.98	
Corner Slab No 115	2	3.29				0.30	1.98	
Corner Slab No 116	2	3.48				0.30	2.09	
Corner Slab No 117	2	3.66				0.30	2.20	
Corner Slab No 118	2	4.03				0.30	2.42	
Corner Slab No 119	2	3.29				0.30	1.98	
Corner Slab No 120	2	3.66				0.30	2.20	

Scanned with CamScanner

CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Area B (m)	D (m)	QTY	REMARKS
Corner Slab No 121	2	4.03				0.30		
Corner Slab No 122	2	4.03				0.30	2.42	
Corner Slab No 123	2	3.66				0.30	2.42	
Corner Slab No 124	2	4.03				0.30	2.20	
Corner Slab No 125	2	3.48				0.30	2.42	
Corner Slab No 126	2	4.03				0.30	2.09	
Corner Slab No 127	2	3.66				0.30	2.42	
Corner Slab No 128	2	3.29				0.30	2.20	
Corner Slab No 129	2	3.48				0.30	1.98	
Corner Slab No 130	2	4.03				0.30	2.09	
Corner Slab No 131	2	3.29				0.30	2.42	
Corner Slab No 132	2	3.66				0.30	1.98	
Corner Slab No 133	2	4.03				0.30	2.20	
Corner Slab No 134	2	3.66				0.30	2.42	
Corner Slab No 135	2	4.03				0.30	2.20	
Corner Slab No 136	2	3.29				0.30	2.42	
Corner Slab No 137	2	3.48				0.30	2.20	
Corner Slab No 138	2	3.29				0.30	2.42	
Corner Slab No 139	2	4.03				0.30	1.98	
Corner Slab No 140	2	4.03				0.30	2.09	
Corner Slab No 141	2	3.66				0.30	1.98	
Corner Slab No 142	2	3.66				0.30	2.42	
Corner Slab No 143	2	3.48				0.30	2.42	
Corner Slab No 144	2	3.29				0.30	2.20	
Corner Slab No 145	2	4.03				0.30	2.20	
Corner Slab No 146	2	3.66				0.30	2.09	
Corner Slab No 147	2	3.66				0.30	2.42	
Corner Slab No 148	2	3.29				0.30	2.20	
Corner Slab No 149	2	3.48				0.30	2.20	
Corner Slab No 150	2	2.75				0.30	1.98	
Corner Slab No 151	2	4.03				0.30	2.09	
Corner Slab No 152	2	3.29				0.30	1.65	
Corner Slab No 153	2	3.29				0.30	2.42	
Corner Slab No 154	2	3.48				0.30	1.98	
Corner Slab No 155	2	4.58				0.30	1.98	
Corner Slab No 156	2	4.39				0.30	2.09	
Corner Slab No 157	2	3.66				0.30	2.75	
Corner Slab No 158	2	3.29				0.30	2.64	
Corner Slab No 159	2	3.48				0.30	2.20	
Corner Slab No 160	2	4.03				0.30	1.98	
Corner Slab No 161	2	4.58				0.30	2.09	
Corner Slab No 162	2	4.39				0.30	2.42	
Corner Slab No 163	2	3.29				0.30	2.75	
Corner Slab No 164	2	3.66				0.30	2.64	
Corner Slab No 165	2	4.03				0.30	1.98	
Corner Slab No 166	2	3.66				0.30	2.20	
Corner Slab No 167	2	3.29				0.30	2.42	
Corner Slab No 168	2	3.29				0.30	2.20	
Corner Slab No 169	2	3.48				0.30	1.98	
Corner Slab No 170	2	3.66				0.30	1.98	
						0.30	2.09	
						0.30	2.20	

Scanned with CamScanner

CHAINAGE / Land Mark	NO	L (m)	B (m)	BI (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 171	2	4.03				0.30	2.42	
Corner Slab No 172	2	3.29				0.30	1.98	
Corner Slab No 173	2	3.66				0.30	2.20	
Corner Slab No 174	2	4.03				0.30	2.42	
Corner Slab No 175	2	4.03				0.30	2.42	
Corner Slab No 176	2	3.66				0.30	2.20	
Corner Slab No 177	2	4.03				0.30	2.42	
Corner Slab No 178	2	3.48				0.30	2.09	
Corner Slab No 179	2	4.03				0.30	2.42	
Corner Slab No 180	2	3.66				0.30	2.20	
Corner Slab No 181	2	3.29				0.30	1.98	
Corner Slab No 182	2	3.48				0.30	2.09	
Corner Slab No 183	2	4.03				0.30	2.42	
Corner Slab No 184	2	3.29				0.30	1.98	
Corner Slab No 185	2	3.66				0.30	2.20	
Corner Slab No 186	2	4.03				0.30	2.42	
Corner Slab No 187	2	3.66				0.30	2.20	
Corner Slab No 188	2	4.03				0.30	2.42	
Corner Slab No 189	2	3.29				0.30	1.98	
Corner Slab No 190	2	3.48				0.30	2.09	
Corner Slab No 191	2	3.29				0.30	1.98	
Mohan Kumar Nagar 74								
Corner Slab No 1	2	4.03				0.30	2.42	
Corner Slab No 2	2	3.66				0.30	2.20	
Corner Slab No 3	2	3.66				0.30	2.20	
Corner Slab No 4	2	3.48				0.30	2.09	
Corner Slab No 5	2	3.29				0.30	1.98	
Corner Slab No 6	2	4.03				0.30	2.42	
Corner Slab No 7	2	3.66				0.30	2.20	
Corner Slab No 8	2	3.29				0.30	1.98	
Corner Slab No 9	2	3.48				0.30	2.09	
Corner Slab No 10	2	2.75				0.30	1.65	
Corner Slab No 11	2	4.03				0.30	2.42	
Corner Slab No 12	2	3.29				0.30	1.98	
Corner Slab No 13	2	3.29				0.30	1.98	
Corner Slab No 14	2	3.48				0.30	2.09	
Corner Slab No 15	2	4.58				0.30	2.75	
Corner Slab No 16	2	4.39				0.30	2.64	
Corner Slab No 17	2	3.66				0.30	2.20	
Corner Slab No 18	2	3.29				0.30	1.98	
Corner Slab No 19	2	3.48				0.30	2.09	
Corner Slab No 20	2	4.03				0.30	2.42	
Corner Slab No 21	2	4.58				0.30	2.75	
Corner Slab No 22	2	4.39				0.30	2.64	
Corner Slab No 23	2	3.29				0.30	1.98	
Corner Slab No 24	2	3.66				0.30	2.20	
Corner Slab No 25	2	4.03				0.30	2.42	
Corner Slab No 26	2	3.66				0.30	2.20	
Corner Slab No 27	2	3.29				0.30	1.98	

Executive Engineer
Rajajinagara Nagara Division
Bruhat Bangalore Mahanagara Palike
Bangalore - 560 064.

Scanned with CamScanner

CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 28	2	3.29				0.30	1.98	
Corner Slab No 29	2	3.48				0.30	2.09	
Corner Slab No 30	2	3.66				0.30	2.20	
Corner Slab No 31	2	4.03				0.30	2.42	
Corner Slab No 32	2	3.29				0.30	1.98	
Corner Slab No 33	2	3.66				0.30	2.20	
Corner Slab No 34	2	4.03				0.30	2.42	
Corner Slab No 35	2	4.03				0.30	2.42	
Corner Slab No 36	2	3.66				0.30	2.20	
Corner Slab No 37	2	4.03				0.30	2.42	
Corner Slab No 38	2	3.48				0.30	2.09	
Corner Slab No 39	2	4.03				0.30	2.42	
Corner Slab No 40	2	3.66				0.30	2.20	
Corner Slab No 41	2	3.29				0.30	1.98	
Corner Slab No 42	2	3.48				0.30	2.09	
Corner Slab No 43	2	4.03				0.30	2.42	
Corner Slab No 44	2	3.29				0.30	1.98	
Corner Slab No 45	2	3.66				0.30	2.20	
Corner Slab No 46	2	4.03				0.30	2.42	
Corner Slab No 47	2	3.66				0.30	2.20	
Corner Slab No 48	2	4.03				0.30	2.42	
Corner Slab No 49	2	3.29				0.30	1.98	
Corner Slab No 50	2	3.48				0.30	2.09	
Corner Slab No 51	2	3.29				0.30	1.98	
Corner Slab No 52	2	4.03				0.30	2.42	
Corner Slab No 53	2	4.03				0.30	2.42	
Corner Slab No 54	2	3.66				0.30	2.20	
Corner Slab No 55	2	3.66				0.30	2.20	
Corner Slab No 56	2	3.48				0.30	2.09	
Corner Slab No 57	2	3.29				0.30	1.98	
Corner Slab No 58	2	4.03				0.30	2.42	
Corner Slab No 59	2	3.66				0.30	2.20	
Corner Slab No 60	2	4.03				0.30	2.42	
Corner Slab No 61	2	3.29				0.30	1.98	
Corner Slab No 62	2	4.03				0.30	2.42	
Corner Slab No 63	2	3.48				0.30	2.09	
Corner Slab No 64	2	3.29				0.30	1.98	
Corner Slab No 65	2	3.66				0.30	2.20	
Corner Slab No 66	2	3.29				0.30	1.98	
Corner Slab No 67	2	3.48				0.30	2.09	
Corner Slab No 68	2	2.75				0.30	1.65	
Corner Slab No 69	2	4.03				0.30	2.42	
Corner Slab No 70	2	3.29				0.30	1.98	
Corner Slab No 71	2	3.29				0.30	1.98	
Corner Slab No 72	2	3.48				0.30	2.09	
Corner Slab No 73	2	4.58				0.30	2.75	
Corner Slab No 74	2	4.39				0.30	2.64	
Corner Slab No 75	2	3.66				0.30	2.20	
Corner Slab No 76	2	3.29				0.30	1.98	

Executive Engineer
Electrical Hazard Division
Bangalore Metro Rail Corporation Ltd.
Bangalore - 560 027.

Scanned with CamScanner

CHAINAGE / Land Mark	NO	L (m)	B (m)	B1 (m)	Avg B (m)	D (m)	QTY	REMARKS
Corner Slab No 77	2	3.48				0.30	2.09	
Corner Slab No 78	2	4.03				0.30	2.42	
Corner Slab No 79	2	4.58				0.30	2.75	
Corner Slab No 80	2	4.39				0.30	2.64	
Corner Slab No 81	2	3.29				0.30	1.98	
Corner Slab No 82	2	3.66				0.30	2.20	
Corner Slab No 83	2	4.03				0.30	2.42	
Corner Slab No 84	2	3.66				0.30	2.20	
Corner Slab No 85	2	3.29				0.30	1.98	
Corner Slab No 86	2	3.29				0.30	1.98	
Corner Slab No 87	2	3.48				0.30	2.09	
Corner Slab No 88	2	3.66				0.30	2.20	
Corner Slab No 89	2	4.03				0.30	2.42	
Corner Slab No 90	2	3.29				0.30	1.98	
Corner Slab No 91	2	3.66				0.30	2.20	
Corner Slab No 92	2	4.03				0.30	2.42	
Corner Slab No 93	2	4.03				0.30	2.42	
Corner Slab No 94	2	3.66				0.30	2.20	
Corner Slab No 95	2	4.03				0.30	2.42	
Corner Slab No 96	2	3.48				0.30	2.42	
Corner Slab No 97	2	4.03				0.30	2.20	
Corner Slab No 98	2	3.66				0.30	2.42	
Corner Slab No 99	2	3.29				0.30	2.09	
Corner Slab No 100	2	3.48				0.30	2.42	
Corner Slab No 101	2	4.03				0.30	2.20	
Corner Slab No 102	2	3.29				0.30	1.98	
Corner Slab No 103	2	3.66				0.30	2.42	
Corner Slab No 104	2	4.03				0.30	2.20	
Corner Slab No 105	2	3.66				0.30	2.42	
Corner Slab No 106	2	4.03				0.30	2.20	
Corner Slab No 107	2	3.29				0.30	2.42	
Corner Slab No 108	2	3.48				0.30	1.98	
Corner Slab No 109	2	3.29				0.30	2.09	
Corner Slab No 110	2	4.03				0.30	1.98	
Corner Slab No 111	2	4.03				0.30	2.42	
Corner Slab No 112	2	3.66				0.30	2.42	
Corner Slab No 113	2	3.66				0.30	2.20	
Corner Slab No 114	2	3.48				0.30	2.20	
Corner Slab No 115	2	3.29				0.30	2.09	
Corner Slab No 116	2	4.03				0.30	1.98	
Corner Slab No 117	2	3.66				0.30	2.42	
Corner Slab No 118	2	4.03				0.30	2.20	
Corner Slab No 119	2	3.29				0.30	2.42	
Corner Slab No 120	2	4.03				0.30	1.98	
Corner Slab No 121	2	3.48				0.30	2.42	
Corner Slab No 122	2	3.29				0.30	2.09	
Corner Slab No 123	2	3.66				0.30	1.98	
Corner Slab No 124	2	3.29				0.30	2.20	
Corner Slab No 125	2	3.48				0.30	1.98	
Corner Slab No 126	2	2.75				0.30	2.09	
							1.65	

Scanned with CamScanner